10 CFR 2.201	SAFETY	INSPECTI	ON		
		, sian na pangananana		Page 1 of	
HOCIDAY MAIL MODERNER BUILDING SUITE NO.6 HOCIDAY MAIL MODERNERD MA 56560		2. REGIONAL OFFICE REGION III U.S. NUCLEAR REGULATORY COMMISSION 799 ROOSEVELT ROAD GLEN ELLYN IL 60137			
3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S	6)	5. DATE OF IN	SPECTION	
080-18463 22-243			JANUARY 10, 1994		
LICENSEE: The inspection was an examination of the act Regulatory Commission (NRC) rules and regulatory procedures and representative records, intervitellows:	lations and the condition	s of your license.	The inspection consiste	ed of selective examinations of	
Within the scope of this inspection,	no violations were observ	red.			
The inspector also verified the steps questions on those actions at this tile Juring this inspection certain of you	me.				
NOTICE OF VIOLATION, which is re	quired to be posted in ac	cordance with 10 (FR 19.11.		
Α			Wi	as not properly posted to	
indicate the presence of a				10 CFR 20.203(b),(c),(d),(e) or 34.42.	
В.	В			sealed sources were not	
performed at the proper frequ	uencies. 10 CFR	or l	icense Condition Num	ber	
C. Records of	C. Records of			were not properly maintained.	
	D. Documents were not properly posted or otherwise made available. 10 CFR 19.11.			PUBLIC	
E. Reports or notification of	or License Condition N	umster I	w	ere not made in accordance with	
processor of the contract of t	F. THEN 8 OF LICENSE PENELVEL (5.25-89) REMORES ANDUMLICATIONS				
RETERMINE F					
Zem eksed Ar					
	DECTED INDIVI	Ou/Aus William	AT LEAST.	TWO UEARS	
SIGNATURE - LICENSEE	DATE	SIGNATURE - N	RC INSPECTOR	DATE	
The state of the s				1-10-94	