

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONTROL BLOCK: ①

0 1 | N | J | S | G | S | 2 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5
8 9 14 15 25 26 57 CAT 58

CON'T

0 1 | R | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 1 | 1 | 7 | 0 | 5 | 1 | 7 | 8 | 1 | 8 | 0 | 6 | 1 | 6 | 8 | 1 | 9
8 60 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES ⑩

0 2 | The control operator noticed the Rod Position Indicator for bank 1B4
0 3 | was off scale. Action Statement 3.1.3.2.1 was entered at 2200 hours on
0 4 | May 17, 1981.

0 5 |
0 6 |
0 7 |
0 8 |

0 9 | R | B | 11 | E | 12 | A | 13 | C | R | D | R | V | E | 14 | Z | 15 | Z | 16 |
7 8 9 10 11 12 13 14 15 16 17 18 19 20

17 | LER RO | E | 18 | 1 | 19 | 0 | 1 | 9 | 20 | 0 | 3 | 21 | L | 22 | 0 |
REPORT NUMBER 21 22 23 24 25 26 27 28 29 30 31

ACTION TAKEN | FUTURE ACTION | EFFECT ON PLANT | SHUTDOWN METHOD | HOURS | ATTACHMENT SUBMITTED | NPRD-4 FORM SUB. | PRIME COMP. SUPPLIER | COMPONENT MANUFACTURER
B | 18 | Z | 19 | Z | 20 | Z | 21 | 0 | 0 | 0 | 0 | Y | 23 | Y | 24 | L | 25 | Z | 9 | 9 | 9 | 26
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS ⑰

1 0 | Investigation disclosed that the Signal Conditioning Module was out of
1 1 | calibration. The module was recalibrated and the system was tested
1 2 | satisfactorily. Action Statement 3.1.3.2.1 was terminated at 1610 hours
1 3 | on May 18, 1981.

1 4 |
1 5 | B | 28 | 0 | 0 | 0 | 29 | N/A | A | 31 | Operator Observation
7 8 9 10 11 12 13 44 45 46 80

1 6 | Z | 33 | Z | 34 | N/A | N/A |
7 8 9 10 11 12 44 45 80

1 7 | 0 | 0 | 0 | 37 | Z | 38 | N/A |
7 8 9 10 11 12 44 45 80

1 8 | 0 | 0 | 0 | 40 | N/A |
7 8 9 10 11 12 44 45 80

1 9 | Z | 42 | N/A |
7 8 9 10 11 12 44 45 80

2 0 | N | 44 | N/A |
7 8 9 10 11 12 44 45 80

8209010035 810616
PDR ADOCK 05000311
S PDR

NRC USE ONLY

NAME OF PREPARER J. J. Espey

PHONE 609-935-0998