



August 24, 1982  
L-82-367

RECEIVED  
REG. DIV.  
AUG 24 1982

Mr. James P. O'Reilly  
Regional Administrator, Region II  
U.S. Nuclear Regulatory Commission  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

RE: St. Lucie Unit 2  
Docket No. 50-389  
Fan Belt Problems During Initial  
Startup of Diesel Generator

On February 10, 1982, Florida Power & Light Company (FPL) notified the Region II Office of Inspection and Enforcement, in accordance with the requirements of 10 CFR 50.55(e), of a potential deficiency regarding the fan belts on diesel generators 2A and 2B. An interim report submitted to you on June 3, 1982 stated that a final report would be submitted by August 20, 1982. We are still working on this problem and expect to submit a final report by September 30, 1982.

Very truly yours,

*Robert E. Uhrig*  
Robert E. Uhrig  
Vice President  
Advanced Systems and Technology

REU/sej

cc: Director of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

8209020306 820824  
PDR ADOCK 05000389  
S PDR

OFFICIAL COPY

IE 27