,	LICENSEE EVENT REPORT Attachment to AECM-82/364
	CONTROL BLOCK: Page 1 of 1 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	M S G G S 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 EICENSE COCE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58
CON'T 0 1 7 8	REPORT L 6 0 5 0 0 0 4 1 6 7 0 7 2 9 8 2 8 0 8 2 6 8 2 9  EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10  On 7/29 a Limiting Condition for Operation was entered under T.S.3.3.7.12 due
0 3	to the fuel handling area ventilation radiation monitoring sample pump being
0 4	removed from service for maintenance. A preventive maintenance inspection
0 5	revealed that the Bl pump had an oil leak. The work order was mistakenly
0 6	written to replace the B2 pump. The error was discovered on 7/30 after
0 7	the B2 pump was replaced and tested.
08	
7 8	SYSTEM CAUSE CAUSE SUBCODE SUB
	ACTION FUTURE SEFECT SHUTDOWN HOURS 22 ATTACHMENT FORM SUB. SUPPLIER COMPONENT MANUFACTURER SUBMITTED FORM SUB. SUPPLIER SUPPLIE
1 0	
	taken in accordance with T.S.3.3.7.12. starting on 8/1 (See LER 82-019/01 T-0).
1 2	The pump is part of the N1D17-P003 monitoring sample panel. The event is
1 3	being reported in accordance with T.S.6.9.1.13.b. This is considered the
	final report.  9 FACULTY  ON METHOD OF
1 5	STATUS SPOWER OTHER STATUS OF DISCOVERY DISCOVERY DESCRIPTION (32)    H   28   0   0   0   29   NA   B   31   Preventive Maintenance   80
	ACTIVITY CONTENT SELEASED OF RELEASE AMOUNT OF ACTIVITY 35  Z 33 Z 34 NA  PERSONNEL EXPOSURES  AMOUNT OF ACTIVITY 35  NA  LOCATION OF RELEASE 36  NA  80
1 7	NUMBER 174PE DESCRIPTION (39) NA 11 12 13 13 NA
18	PERSONNEL INJURIES NUMBER DESCRIPTION 41  NA
7 8	9 11 12 LOSS OF OR DAMAGE TO FACILITY (43) 200020308 820826
1 9	TYPE DESCRIPTION NA PDR ADDCK 05000416 PDR 80
[2]0	PUBLICITY ISSUED DESCRIPTION 45  NA
7 8	9 Original Signed By: Ron Byrd 68 69 80.5
	NAME OF PREPARER PHONE: