Attachment to AECM-82/367

Page 1 of 1
CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 M S G G S 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 57 CAT 58
CON'T  O 1 SOURCE L 6 0 5 0 0 0 4 1 6 7 0 7 2 2 8 2 8 0 8 2 6 8 2 9  EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10  O 2 During a special inspection by the Fire Protection/Safety Coordinator,
[0]3   penetration seal CV-19G was found not installed. The HVAC penetration is
0 4   located on the 189 ft. elevation east passageway room OC711 of the Control
[0] Building. The event is being reported pursuant to T.S.6.9.2.
061
0 7
08
SYSTEM   CAUSE   CODE
The open penetration is a construction error. The penetration will be
[1] [ sealed as soon as procedures and qualified personnel are available. An
hourly fire watch is being conducted pursuant to T.S.3.7.7.a in the
interim. A final report should be submitted within the next 60 days.
7 8 9 FACILITY STATUS  \$ POWER OTHER STATUS  OTHER STATUS
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35  1 6 Z Z 33 Z 34 NA
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39  NA  PERSONNEL INJURIES  NA  80
PERSONNEL INJURIES NUMBER DESCRIPTION 41  NA
1 8 9 11 12 80 LOSS OF DR DAMAGE TO FACILITY (43)
1 9 Z 42 NA
PUBLICITY   SSUED DESCRIPTION (45)   NA S PDR
Original Signed by: Ron Byrd  NAME OF PREPARER  PHONE:

PHONE:\_\_