LICENSEE EVENT REPORT

	The state of the s
	CONTROL BLOCK:
7 3	M I D C C 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 CAT 58
0 1 2 8	SOURCE 1 0 5 0 0 0 3 1 5 7 0 7 2 8 8 2 3 0 8 2 4 8 2 9
0 2	DURING REFUELING OF UNIT 1 AND NORMAL OPERATION OF UNIT 2, FIRE DOOR #415, CONNECTING
0 3	DOOR BETWEEN CONTROL ROOMS, WOULD NOT FULLY CLOSE ON TWO OCCASIONS. THIS CONSTITUTED,
0 4	AN INOPERABLE PENETRATION FIRE BARRIER, CONTRARY TO T.S. 3.7.10. ACTION REQUIREMENTS:
0 [5]	WERE MET AND PUBLIC HEALTH AND SAFETY WERE NOT AFFECTED.
0 6	
0 7	
7 8	
j 9 7 8	SYSTEM CAUSE CODE SUBCODE SUBC
	17 REPORT NUMBER 21 22 23 24 26 27 28 29 30
	ACTION FUTURE COMPONENT SHUTDOWN HOURS 22 ATTACHMENT NPRO-4 PRIME COMP. COMPONENT SUBMITTED FORM SUB. SUPPLIER MANUFACTURER
	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)
1]3	THE DOOR WAS UNABLE TO CLOSE AGAINST THE VENTILATION FLOW FROM UNIT 1 INTO UNIT 2.
	THE INCREASED FLOW WAS DUE TO THE UNIT 2 CABLE VAULT DOOR BEING OPEN DURING WORK IN
1 2	THE AREA. THE DOOR CLOSURE MECHANISM WAS ADJUSTED AND THE DOOR OPERATED
113	SATISFACTORILY.
1 5	H 28 O O O O O O O O O O O O O O O O O O
	LEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA
1 7	ONUMBER DESCRIPTION 39 NA
1 8	O O O O O O O O O O O O O O O O O O O
1 9	OSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION NA
2 2 1	PUBLICITY SUED DESCRIPTION 45 NA S PDR ADDCK 05000315 PDR
a. :	NAME OF PREPARER R. H. PIEHL PHONE 616-465-5901