

LICENSEE EVENT REPORT

Attachment to AECM-82/366

Page 1 of 1

CONTROL BLOCK: 1 | | | | | | 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | M | S | G | G | S | 1 | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | 5

CON'T
0 1 | L | 6 | 0 | 5 | 0 | 0 | 0 | 4 | 1 | 6 | 7 | 0 | 7 | 3 | 0 | 8 | 2 | 8 | 0 | 8 | 2 | 6 | 8 | 2 | 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
0 2 | On 8/2/82 it was discovered that there was no documentation to verify
0 3 | secondary containment integrity as required every 31 days by T.S.4.6.6.1
0 4 | secondary containment was therefore declared inoperable and core
0 5 | alterations suspended. The event is being reported pursuant to T.S.6.1.9.13.c.
0 6 |
0 7 |
0 8 |

0 9 | X | X | 11 | D | 12 | Z | 13 | Z | Z | Z | Z | Z | Z | 14 | Z | 15 | Z | 16

17 | LER/RO REPORT NUMBER | 8 | 2 | 21 | 22 | - | 23 | 0 | 3 | 0 | 24 | 26 | / | 27 | 0 | 3 | 28 | 29 | L | 30 | - | 31 | X | 32

1 0 | No procedures existed at the time to conduct the surveillance test. A
1 1 | temporary signoff list was generated and completed on 7/30 to verify
1 2 | secondary containment integrity. Procedure 06-OP-1T48-M-0003 was
1 3 | approved on 8/12 to meet requirements of T.S.4.6.6.1. This is intended
1 4 | as a final report.
1 5 | H | 28 | 0 | 0 | 0 | 29 | NA | 30 | A | 31 | Incidental Observation | 32

8209020570 820826
PDR ADOCK 05000416
S PDR NA

Original Signed By: Ron Byrd

NAME OF PREPARER

PHONE: