



CALVERT CLIFFS NUCLEAR POWER PLANT
1650 CALVERT CLIFFS PARKWAY • LUSBY, MARYLAND 20657-4702

CHARLES H. CRUSE
PLANT GENERAL MANAGER
CALVERT CLIFFS

February 11, 1994

U. S. Nuclear Regulatory Commission
Washington, DC 20555

ATTENTION: Document Control Desk

SUBJECT: Calvert Cliffs Nuclear Power Plant
Unit Nos. 1 & 2; Docket Nos. 50-317 & 50-318
Non-Compliance With NPDES Permit No. MD0002399A

In accordance with Section 3.2 of Appendix B, "Environmental Protection Plan (Non-Radiological) Technical Specifications," attached is a copy of a letter reporting a recent non-compliance with the NPDES permit for Calvert Cliffs Nuclear Power Plant. This letter is dated February 4, 1994.

Should you have any questions regarding this matter, we will be pleased to discuss them with you.

Very truly yours,

CHC/WDM/bjd

Attachment: As Stated

cc: D. A. Brune, Esquire
J. E. Silberg, Esquire
R. A. Capra, NRC
D. G. McDonald, Jr., NRC
T. T. Martin, NRC
P. R. Wilson, NRC
R. I. McLean, DNR
J. H. Walter, PSC

280019

9403010167 940211
PDR ADOCK 05000317
S PDR

IEZZ
11



CALVERT CLIFFS NUCLEAR POWER PLANT
1650 CALVERT CLIFFS PARKWAY • LUSBY, MARYLAND 20657-4702

CHARLES H. CRUSE
PLANT GENERAL MANAGER
CALVERT CLIFFS

February 4, 1994

Michael Reahl
State of MD - Department of the Environment
Water Management Administration
2400 Broening Highway
Baltimore, Maryland 21224

Dear Mr. Reahl:

RE: NPDES Permit Special Condition A3 Noncompliance January 31, 1994
NPDES Discharge Permit MD0002399A, State Permit 86-DP-0187A

On January 31, 1994, during a routine surveillance of the continuous monitoring equipment required by the Calvert Cliffs Nuclear Power Plant site NPDES permit, the plant intake embayment instrumentation sample pump was found to be not working. During this time period there was no indication of a noncompliance with effluent limitations.

The sample pump was out of service for an undetermined amount of time but definitely less than 72 hours. The actual length of time the pump was out of service will be determined when the magnetic record is evaluated at the end of the month. The sample pump was immediately replaced and the sample flow restored within one hour of failure discovery. This matter was reported to your department on February 1, 1994 at 11:00 o'clock.

Sincerely,

Charles H. Cruse

CHC:JAS

cc: E.I. Bauereis
J.F. Stine
R.A. Kreger
Nuclear Regulatory Commission