PRINTING TRANSPORTER



P.O. BOX 270 HARTFORD, CONNECTICUT 06101 (203) 666-6911

Mr. Ronald C. Haynes
Regional Administrator, Region 1
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

September 1, 1982 MP-1-2149

Reference:

Provisional License DPR-21

Docket No. 50-245

Reportable Occurrence RO-82-15/3L, 82-16/1T

Dear Mr. Haynes:

This letter forwards the Licensee Event Reports for Reportable Occurrence RO-15/3L, required to be submitted within 30 days pursuant to Millstone Unit 1 Technical Specification 6.9.1.9.b. and RO-82-16/1T, required to be submitted within 14 days pursuant to the requirements of Millstone Unit 1 Technical Specification 6.9.1.8.b. The plant incident report (PIR) for RO-82-15/3L could not be investigated within the 30 day time limit because an investigation required drywell entry. The PIR for RO-82-16/1T was originally classified as a 30 day reportable and inadvertently misplaced. After reviewing the PIR for a second time the PIR was reclassified as prompt reportable. An additional three copies of the reports are enclosed.

Yours truly,

NORTHEAST NUCLEAR ENERGY COMPANY

E. J. Mroczka
Station Superintendent
Millstone Nuclear Power Station

EJM/TST:mo

Attachment:

LER RO-82-15/3L, 82-16/1T

cc: Director, Office of Inspection and Enforcement, Washington, D. C. (30) Director, Office of Management Information and Program Control, Washington, D. C. (3) U. S. Nuclear Regulatory Commission, c/o Document Management Branch,

Washington, D. C. 20555