



Donald A. Wells
Manager Quality Assurance
(313) 237-9657
2000 Second Avenue
Detroit, Michigan 48226
(313) 237-8000

August 27, 1982
EF2-59389

Mr. James G. Keppler, Regional Administrator
Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Subject: Interim Report of 10CFR50.55(e) Item on Tubing Within Instrument
Rack Routed Incorrectly (#65)

Dear Mr. Keppler:

This additional interim report on the tubing within the instrument rack being routed incorrectly has been prepared to provide you with the current status of this problem.

The problem was originally reported to Mr. J. Konklin of NRC Region III by Project Quality Assurance's Mr. E.L. Thompson, Acting Supervisor-Construction Quality Assurance, on April 1, 1982.

This condition appeared to be the result of improperly routed tubing within an Instrument Rack supplied by York Electro-Panel Control Co., Inc. Inspections by the site contractor responsible for routing tubing up to the rack, revealed that the tubing from two (2) valves to the top side of the rack had been interchanged. In other words, York Electro-Panel's Fabrication/As-Built drawing shows these two lines opposite from the actual condition on the rack.

Detroit Edison Engineering in Troy was contacted and determined the problem to be potentially reportable under 10CFR50.55(e).

A Deviation Disposition Request (DDR) was written, and dispositioned to re-route the tubing inside the rack to the correct valves. This re-routing has been completed.

Detroit Edison is continuing the evaluation of this deficiency to determine if any further corrective action is necessary.

8209090189 820827
PDR ADOCK 05000341
S PDR

SEP 7 1982


PE27

Mr. James G. Keppler, Regional Administrator
Page Two

August 27, 1982
EF2-59389

Another report on this item, either interim or final, is scheduled to be sent to you on or before December 23, 1982. If you have questions concerning this matter, please contact Mr. G.M. Trahey, Assistant Director-Project Quality Assurance.

Very truly yours,



DAW/DF/cp

cc: Mr. Richard DeYoung, Director
Office of Inspection and Enforcement
Division of Reactor Inspection Programs
Washington, D.C. 20555

Mr. Bruce Little, Resident Inspector
U.S. Nuclear Regulatory Commission
6450 North Dixie Highway
Newport, Michigan 48166

Mr. James G. Keppler, Regional Administrator
Page Three

August 27, 1982
EF2-59389

bcc: T.A. Alessi
J.C. Ard, Jr.
C.R. Bacon
W.F. Colbert
W.M. Everett
W.J. Fahrner
D. Ferencz
E.P. Griffing
C.M. Heidel
W.H. Jens
E. Lusic
P.A. Marquardt/Docket File (2)
E.H. Newton
S.H. Noetzel
J.W. Nunley
J.D. Ryan
L.E. Schuerman
H. Tauber
G.M. Trahey
R.A. Vance/L.E. Eix
A.E. Wegele
Site Document Control
NRC Follow-Up Book/NRC File
Chron File