

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 MIDCC 100-000000-000 41111

01 REPORT SOURCE L 05000315 080482 0910282

02 IN THE COURSE OF A Q.A. SURVEILLANCE TOUR DURING REFUELING, FIRE SEAL W-7006 WAS
03 FOUND TO CONTAIN LESS THAN THE REQUIRED DEPTH OF FOAM SEALANT. THIS CONSTITUTED AN
04 INOPERABLE PENETRATION FIRE BARRIER, CONTRARY TO T.S. 3.7.10. ACTION REQUIREMENTS
05 WERE MET AND PUBLIC HEALTH AND SAFETY WERE NOT AFFECTED. PREVIOUS OCCURRENCES:
06 79/044, 79/055, 81/051 AND, FOR DOCKET 05/316, 81-051.

03 SYSTEM CODE AB CAUSE CODE B CAUSE SUBCODE C COMPONENT CODE XXXXX X COMP SUBCODE Z VALVE SUBCODE Z
17 LER NO REPORT NUMBER 82 EVENT YEAR 82 SEQUENTIAL REPORT NO. 069 OCCURRENCE CODE 03 REPORT TYPE L REVISION NO. 0
ACTION TAKEN B FUTURE ACTION Z EFFECT ON PLANT Z SHUTDOWN METHOD Z HOURS 0000 ATTACHMENT SUBMITTED N NPRD-4 FORM SUB. N PRIME COMP. SUPPLIER A COMPONENT MANUFACTURER Z9999

10 THE SEAL HAD BEEN IMPROPERLY INSTALLED, APPARENTLY DURING CONSTRUCTION. IMMEDIATE
11 REPAIRS WERE MADE PER PLANT PROCEDURE. THE PROCEDURAL REQUIREMENT FOR Q.C.
12 INSPECTION OF FIRE SEAL INSTALLATION AND REPAIR SHOULD PREVENT A RECURRENCE.

15 FACILITY STATUS H % POWER 000 OTHER STATUS NA METHOD OF DISCOVERY B Q.A. PERSONNEL OBSERVATION
16 ACTIVITY CONTENT Z RELEASED OF RELEASE Z AMOUNT OF ACTIVITY NA LOCATION OF RELEASE NA
17 PERSONNEL EXPOSURES NUMBER 0 TYPE Z DESCRIPTION NA
18 PERSONNEL INJURIES NUMBER 0 DESCRIPTION NA
19 LOGS OF OR DAMAGE TO FACILITY TYPE Z DESCRIPTION NA
20 PUBLICITY ISSUED N DESCRIPTION NA

8209090210 820902
PDR ADOCK 05000315
S PDR