

## UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION IV

611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-8064

FEB 23 1994

Docket: 030-20836 License: 25-21479-01

Mattingly Testing Services, Inc.

ATTN: Mark Mattingly

Radiatioin Safety Officer

P.O. Box 3126

Great Falls, Montana 59403

SUBJECT: NRC INSPECTION REPORT 030-20836/94-01 (NOTICE OF VIOLATION)

This refers to the routine, unannounced inspection conducted by Messrs. William H. Radcliffe and Gilbert L. Guerra, Jr., of this office on February 10, 1994. The inspection included a review of activities authorized by Byproduct Materials License 25-21479-01. At the conclusion of the inspection, the findings were discussed with members of your staff.

The inspection was an examination of activities conducted under the license as they relate to radiation safety and to compliance with the Commission's rules and regulations and the conditions of the license. The inspection consisted of selective examinations of procedures and representative records, interviews of personnel, independent measurements, and observation of activities in progress.

Based on the results of this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice of Violation (Notice).

You are required to respond to this letter and should follow the instructions specified in the enclosed Notice when preparing your response. In your response, you should document the specific actions taken and any additional actions you plan to prevent recurrence. After reviewing your response to this Notice, including your proposed corrective actions and the results of future inspections, the NRC will determine whether further NRC enforcement action is necessary to ensure compliance with NRC regulatory requirements.

The inspectors noted that the overall radiation safety program seemed adequately managed and that radiation safety regarding the use of radiography exposure devices was regularly discussed with employees. Three radiographers and two assistants utilizing four radiography trucks and six exposure devices were currently employed. Field audits of radiographers and assistants had been conducted coutinely as required. This inspection did not include observations of work practices at temporary jobsites.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be placed in the NRC Public Document Room.

9403080055 940223 PDR ADOCK 03020836 C PDR F07

The responses directed by this letter and the enclosed Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, Pub. L. No. 96.511.

Should you have any questions concerning this letter, please contact the inspector identified above at (817) 860-8100.

Sincerely,

Dwight D. Chamberlain, Acting Director

Division of Radiation Safety

and Safeguards

Enclosure:

Appendix - Notice of Violation

CC:

Montana Radiation Control Program Director

bcc: DMB - Original (IE-07) LJCallan DDChamberlain LWCamper RAScarano, RV MMessier, OC/LFDCB (4503) \*WLFisher \*CLCain \*GLGuerra \*WHRadcliffe \*NMIB \*MIS System \*RIV Files (2)

\*W/IFS Form

RIV:NMIB	4 NMIB GVG	C:NMIB (NAC	AD: DRSS, AP	

DDChamberlain

2/22/94

CLCain

2/22/94

WHRadcliffe

2/21/94

GLGuerra:cd

2/22/94

bcc: DMB - Original (IE-07) LJCallan DDChamberlain LWCamper RAScarano, RV MMessier, OC/LFDCB (4503) \*WLFisher \*CLCain \*GLGuerra \*WHRadcliffe \*NMIB \*MIS System \*RIV Files (2)

\*W/IFS Form

RIV:NMIB	NMIB GVG	C:NMIB (MC	AD: DRSS, 90
GLGuerra:cd	WHRadcliffe	CLCain	DDChamberlain
2/22/94	2/21/94	2/22/94	2/22/94