

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 M I D C C 1 0 0 - 0 0 0 0 0 - 0 0 4 1 1 1 1  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

CON'T  
0 1 REPORT SOURCE L 0 5 0 0 0 3 1 5 0 8 1 6 8 2 0 9 0 1 8 2  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  
0 2 DURING REFUELING OPERATIONS, AN OPERATOR DISCOVERED FIRE DOOR #373 UNABLE TO LATCH.

0 3 THIS CONDITION CONSTITUTED AN INOPERABLE PENETRATION FIRE BARRIER, CONTRARY TO T.S.

0 4 3.7.10. ACTION REQUIREMENTS WERE MET AND PUBLIC HEALTH AND SAFETY WERE NOT AFFECTED.

0 5 PREVIOUS OCCURRENCES: 82-031, 82-033, 82-038, 82-040. DOCKET 05/316: 82-043,

0 6 82-045, 82-040.

0 7 \_\_\_\_\_

0 8 \_\_\_\_\_

0 9 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE  
A B X Z X X X X X X Z Z

17 LER NO REPORT NUMBER 8 2  
EVENT YEAR 8 2  
SEQUENTIAL REPORT NO. 0 6 7  
OCCURRENCE CODE 0 3  
REPORT TYPE L  
REVISION NO. 0

ACTION TAKEN B G  
FUTURE ACTION G  
EFFECT ON PLANT Z  
SHUTDOWN METHOD Z  
HOURS 0 0 0 0  
ATTACHMENT SUBMITTED N  
NPRO-4 FORM SUB. N  
PRIME COMP. SUPPLIER A  
COMPONENT MANUFACTURER Z 9 9 9

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 THE FAILURE WAS DUE TO LOOSE AND MISSING SCREWS. SCREWS WERE REPLACED/TIGHTENED AND

1 1 STAKED. INSPECTION PROCEDURE CHANGED TO REQUIRE STAKING OF ALL SCREWS IN DOORS AND

1 2 ASSOCIATED HARDWARE.

1 3 \_\_\_\_\_

1 4 \_\_\_\_\_

1 5 FACILITY STATUS H % POWER 0 0 0 0 OTHER STATUS NA METHOD OF DISCOVERY B DISCOVERY DESCRIPTION OPERATOR OBSERVATION

1 6 ACTIVITY CONTENT Z Z AMOUNT OF ACTIVITY NA LOCATION OF RELEASE NA

1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 TYPE Z DESCRIPTION NA

1 8 PERSONNEL INJURIES NUMBER 0 0 0 DESCRIPTION NA

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z DESCRIPTION NA

2 0 PUBLICATION DESCRIPTION N NA 8209090273 820901 PDR ADOCK 05000315 PDR

NAME OF PREPARER R. H. PIEHL PHONE: 616-465-5901