

APPENDIX A

Notice of Violation

Baltimore Gas and Electric Company
Calvert Cliffs Nuclear Power Plant

Docket/License Nos. 50-317; DPR-53
50-318; DPR-69

During an NRC inspection conducted from January 19, 1994, through January 21, 1994, a violation of NRC requirements was identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions, " 10 CFR Part 2, Appendix C, the following violation was identified.

10 CFR 50 Appendix B, Criterion III states in part that design control measures shall provide for verifying or checking the adequacy of design such as by the performance of design reviews or by the performance of a suitable testing program.

Contrary to the above, on or before January 11, 1994, design control measures were not provided for verifying or checking the adequacy of the installation of the Unit 2 voltage regulator sudden pressure trip relays. This failure to verify installation adequacy resulted in the January 12, 1994, Unit 2 trip and partial loss of offsite power.

This is a Severity Level IV violation (Supplement 1).

Pursuant to the provisions of 10 CFR 2.201, Baltimore Gas and Electric Company is hereby required to submit a written statement or explanation to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, D.C. 20555, with a copy to the Regional Administrator, Region I, and a copy to the NRC Resident Inspector, within 30 days of the date of the letter transmitting this Notice of Violation (Notice). This reply should be clearly marked as a "Reply to a Notice of Violation" and should include for each violation: (1) the reason for the violation, or, if contested, the basis for disputing the violation, (2) the corrective steps that have been taken and the results achieved, (3) the corrective steps that will be taken to avoid further violations, and (4) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending the response time.