



SACRAMENTO MUNICIPAL UTILITY DISTRICT □ 6201 S Street, Box 15830, Sacramento, California 95813; (916) 452-3211

August 16, 1982
EQC 82-46B

DIRECTOR OF NUCLEAR REACTOR REGULATION
ATTENTION JOHN F STOLZ CHIEF
OPERATING REACTORS BRANCH 4
U S NUCLEAR REGULATORY COMMISSION
WASHINGTON D C 20555

DOCKET 50-312
RANCHO SECO NUCLEAR GENERATING STATION UNIT NO. 1
AUXILIARY FEEDWATER HEADER REPAIR - ADDITIONAL INFORMATION

During a meeting held on August 13, 1982 in Washington D.C., it was agreed between Mr. R. Wichert (SMUD) and Mr. J. Stolz (NRC) that a letter would be forwarded to you discussing the following commitment prior to reactor criticality:

The District will submit on or before September 13, 1982, a proposed Technical Specification change which will specify inspection requirements for the stabilized Internal Auxiliary Feedwater Headers. The inspections specified by this proposed Technical Specification change will consist of inspections of all welds used for stabilization of the Internal Header as well as inspections of Internal Header corner welds. The inspections of welds in the Internal Header will be done in such a way that the known cracks in the Internal Header will be inspected and accessible weld areas on the inner plate of the Internal Header will be inspected through each new Auxiliary Feedwater Penetration.

These inspections will be performed and are applicable to the next refueling outage only. Information will be reported to the NRC regarding these inspections in the subsequent Monthly Report. Additional discussions will be held regarding any future inspection of the stabilized Internal Header based on the inspection results.

John J. Mattimoe
John J. Mattimoe
Assistant General Manager
and Chief Engineer

A001

8209100009 820816
PDR ADOCK 05000312
G PDR