NXXIIHEAST UTILITIES



P.O. BOX 270 HARTFORD, CONNECTICUT 06101 (203) 666-6911

RN MASSLACHRISETTS ELECTRIC COMPANY KEWATER POWER COMPANY ENST UTU, CITS, SERVICE COMPANY ENST UTU, CITS, SERVICE COMPANY ENST NUCLEAR THEREY COMPANY

September 3, 1982

Docket No. 50-423 AEC-MP3-285 B10554

Mr. Ronald C. Haynes Region I Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia, PA 19406

References: (1) W. G. Counsil letter to USNRC, Millstone 3; Reporting of Potential Significant Deficiencies in Design and Construction, dated April 15, 1980.

> Millstone Nuclear Power Station, Unit No. 3, Reporting of Potential Significant Deficiencies In Design and Construction: Cracking of Control Rod Guide Tube Support Pins (SD-6)

Gentlemen:

Reference (1) described a potential significant deficiency concerning the cracking of control rod guide tube support pins and committed us to inform you at a later date what corrective and preventative action was being taken. At this time we are still unable to provide you with a final report. However, we are planning to make this information available to you by October 8, 1982.

Very truly yours,

NORTHEAST NUCLEAR POWER COMPANY

W. G. Counsil Senior Vice President

cc: E. J. Brunner