LICENSEE EVENT REPORT

* 1
CONTROL BLOCK:
0 1 M D C C N 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 6 5 TENSE TYPE 30 57 CAT 58
CON'T O 1 SOURCE L G O S O O O O O O O O
EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10) [0 2 For the past 30 days, during start-up and shut down operation, pressur-
[0]3] izer level deviated from the program level by more than +/-5% several
[0]4] times (T.S. 3.4.4). For 5 minutes on August 5, 5 minutes on August 17,
[0]5] 5 minutes on August 22 and several times between 0730and 0830 on August
shutdown operation, pressurizer level deviated from the program band.
O 8 Similar events: 50-317/82-37 and 50-318/82-27.
SYSTEM CAUSE CODE SUBCODE COMPONENT CODE SUBCODE SUBCO
LER/RO
RCS temperature swings of greater than 10 degrees are not uncommon dur-
ing start-up and shutdown operations. These temperature swings can re-
sult in deviations of greater than +/-5% from pressurizer program level.
Re-analysis for justification of relaxation of Technical Specification
is currently in progress.
7 8 9 FACILITY STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 1 5 C 28 0 0 0 29 N/A A 31 Operator Observation 80
ACTIVITY CONTENT PELEASED OF RELEASE AMOUNT OF ACTIVITY 35 1 6 Z 33 Z 34 N/A LOCATION OF RELEASE 36 7 8 9 10 11 N/A 44 45 N/A
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 1 1 12 13 80
PERSONNEL INJURIES NUMBER DESCRIPTION 41
7 8 9 11 12 80 LOSS OF OR DAMAGE TO FACILITY (43)
T 9 Z (42) N/A
7 8 9 10 8209160111 820907 PUBLICITY PDR ADOCK 05000317 NRC USE ONLY
2 0 N 44 DESCRIPTION S PDR
NAME OF PREPARER M. A. Junge PHONE 301-269-4969