

APPENDIX A  
NOTICE OF VIOLATION

ECB Engineers, Incorporated

License No. 45-19548-01

As a result of the inspection conducted on August 2, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violations were identified.

- A. 10 CFR 19.11(a) and (b) require that current copies of Part 19, Part 20, the license, license conditions, documents incorporated into the license, license amendments, and operating procedures be posted, or that a notice describing these documents and where they may be examined, be posted.

Contrary to the above, on August 2, 1982, neither the documents nor the notice were posted.

This is a Severity Level V Violation (Supplement VI).

- B. Condition 14 of License No. 45-19458-01 requires that sealed sources containing byproduct material be tested for leakage and/or contamination at intervals not to exceed six months.

Contrary to the above, as of August 2, 1982, sealed source containing 10 millicuries of Cesium 137 had not been tested for contamination or leakage since November 25, 1980, an interval of more than six months.

This is a Severity Level IV Violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, you are hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violations; (2) the reasons for the violations if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Date: August 16, 1982