LICENSEE EVENT REPORT

-	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	N J S G S 2 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5 5.
CON'T	REPORT LIG 0 5 0 0 0 3 1 1 7 0 9 0 2 8 2 8 0 9 2 2 8 2 9 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
0 2	At 1350 hours, September 2, 1982, the Control Room Operator received indication
0 3	of low service water flow on No. 23 Containment Fan Coil Unit (CFCU). No. 23
0 4	CFCU was declared inoperable and Action Statement 3.6.2.3.a was entered at 1350 hours.
0 5	
0 6	
0 7	L
0 8	1 80
0 9	SYSTEM CAUSE CODE SUBCODE COMPONENT CODE SUBCODE SUBCO
	LER'RO EVENT YEAR REPORT NO. 17 REPORT NUMBER 21 22 23 24 26 27 28 29 30 30 31 32 ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT FORM SUB. SUPPLIER MANUFACTURER X 18 Z 19 Z 20 Z 21 0 0 0 0 1 2 25 2 9 9 9 26 X 33 34 9 35 36 37 37 40 41 42 43 43 44 47
10	The cause was silt build up in the cooling coils. The service water flow control
11	valve was cycled and the CFCU was tested satisfactorily. At 2019 hours,
1 2	September 2, 1982, No. 23 CFCU was declared operable and Action Statement 3.6.2.3.a
13	was terminated.
14	
_	FACILITY STATUS OTHER STATUS OF DISCOVERY DESCRIPTION 32 E 28 0 8 2 29 NA B 31 Routine Surveillance
1.0	ELEASED OF RELEASE AMOUNT OF ACTIVITY 35 NA LOCATION OF RELEASE 36 NA BO BO
1 7	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 O O O 37 Z 38 NA PERSONNEL INJURIES BO
1 8	NUMBER DESCRIPTION (1)
19	SOUTH STATE OF THE
20	PUBLICITY S210070248 820922 NRC USE ONLY SSUED DESCRIPTION (45) PDR ADDCK 05000311 PDR ADDCK 05000311 S PDR S S S S S S S S S
1	NAME OF PREPARER R. Heller PHONE: 609/935-6000 Ext. 3078