DESIGNATED ORIGINAL

mar

Certified By

## DRIMMAST UTILITIES

. .

General Offices & Selden Street, Berlin, Competieur

PO BOX FTO CONNECTIOUT OF IOT

September 27. 1982 MP-4158

Mr. Ronald C. Haynes Regional Administrator. Region I Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia. Pennsylvania 19406

Reference: Docket Number 60-246 Provisional License DPR-21 Reportable Occurrence 82-18/1P

Dear Mr. Haynes:

This letter is forwarded to provide prompt notification of Reportable Occurrence 82-18/1P as required by the Millstone Unit 1 Technical Specifications.

On September 25, 1982, at 1500 hours while performing a remote visual inspection of the core spray spargers, a crack indication was identified on one of the core spray spargers to junction box welds. Inspection of the remaining three junction boxes revealed no indications. Following an evaluation a report will be submitted to the Nuclear Reactor Regulations (NRR) for review and concurrence. There were no safety implications. The plant is shutdown and core defueled.

Additional information, including immediate and long-term corrective actions, will be provided in a 14-day followup report.

## Yours truly.

NORTHEAST NUCLEAR ENERGY COMPANY

0

E. O. Mroczka Station Superintendent Millstone Muclear Power Station

EJM/TST:mo

ŕ

cc: Director, Office of Management Information and Program Control. Washington, D. C. (2) U.S. Nuclear Regulatory Commission, c/o Document Management Branch. Washington, D. C. 20555