LICENSEE EVENT REPORT

CONTROL BLOCK:
1 I A D A C 1 2 0 0 - 0 0 0 0 0 - 0 0 0 0 0 0 0 0 0 0
OT: SOURCE 60 61 OCKET NUMBER 66 60 EVENT DATE 74 75 REPORT DATE 80
During normal operation, workmen in the RCIC room reported a marked incr
is used townships Subsequent investigation revealed that the dri
ease in room temperature. Subsequent investigation revealed that the dri
ve belt for RCIC room cooling unit 1V-AC-15A was broken. Since redundant
Ols 1V-AC-15B was inoperable for repairs, RCIC pump 1P-226 was inoperable pe
ole Lr T.S.3.5, I and a 30-day LCO was entered. There have been no previous si
[0]7 [milar occurrences.
্তার ৄ
SYSTEM CAUSE CODE SUBCODE COMPONENT CODE SUBCODE SUBCODE SUBCODE
SEQUENTIAL OCCURRENCE REPORT MEVISION NO.
(17) REPORT 8 2 0 5 9 0 3 1 0 31 32 32 33 32 32 33 32 32
ACTION FUTURE EFFECT SHUTDOWN HOURS (22) ATTACHMENT NPRO- PRIME COMP. CONTONENT
LAIS ZIO LZIO LZIO JOIOIO JI IN DE LAIS LXI 91 91 91 91
The drive belt for 1V-AC-15A was broken due to unpredictable random fail
The drive belt was replaced and 1V-AC-15A was returned to service.
Inspection intervals for the belt to be shortened to six months to precl
Inspection intervals for the Bert to be shortened to six months to preci
ude recurrence.
STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION (12)
7 8 2 12 12 13 44 44 44
RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39
117 01010 03 Z 38 NA
PERSONNEL INJURIES NUMBER DESCRIPTION 41
8210130590 821001
TYPE DESCRIPTION PDR ADOCK 05000331 S PDR ADOCK 05000331
PUBLICITY ISSUED DESCRIPTION 45
PIO LNO NA
NAME OF PREPARER Kimuel L. Hill PHONE 319-851-5611 2