No. 82-031/03L-0

Mr. R. C. Haynes, Director Office of Inspection & Enforcement, Region I U.S. Muclear Hegulatory Commission 63: Park Averue King of Prussia, PA 19406

Near Mr. haynes:

This LER deals with the failure of smoke detector S 14 in the "B" emergency switchgear room.

Applicable Tech. Spec is 4.14.C.1

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT	MINISTON .
CONTROL BLOCK:	
0 1 P A P B S 2 0 0 - 0 0 0 0 - 0 0 0 41 1 1 1 1 0 0 57 CAT S	10
CON'T   MEPORT   LIG   5   0   -   0   2   7   7   7   0   8   3   1 8   2   8   1   9   3   0   8   2   8   1   9   3   0   8   2   8   1   9   3   0   8   2   8   1   9   3   0   8   2   9   8   9   9   9   9   9   9   9   9	r̃⊙
[0] While operating at power, during a period c surveillance lest,	
smoke detector S14 in the "B" emergency switchgear room failed to	
old   calibrate to within the limits specified on the surveillance test.	
O D Consequences were minimal since the detector was replaced immediate	ely.
O O Applicable Tech Spec. is 4.14.C.1	
[0]8]	
SYSTEM CAUSE CAUSE COMPONENT CODE SUBCODE SUBCODE	
A B T E T E T E T E T E T E T E T E T E T	ION
THE MILE OF THE PROPERTY OF TH	
ATTACHMENT MERCA PRIME COMP COM	PONENT
COOLS O STO STO TO O O TATO TATO TATO	
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (2)  The cause of this event was a faulty smoke detector, Pyrotronics,	
Model P-SB. The detector was replaced calibrated shocked for	
Operability and returned to service	
[12] Operating and recurred to service.	
O WITHOUT O	. 80
FACILITY SPOWER OTHER STATUS METHOD OF DISCOVERY DESCRIPTION 32    5   E  (20   1  0   0   (30   NA   B  3)   Surveillance test	
ACTIVITY CONTENT 12 ACTIVITY 35 LOCATION OF RELEASE 36	
T G Z 3 Z 30 NA NA NA	*0
NUMBER TYPE DESCRIPTION (9)  17   0   0   0   (37)   2   (38)   NA	
PERSONNEL INJURIES NUMBER DESCRIPTION 41	10
NA NA	80
LOSS OF OR DAMAGE TO PACILITY (3)  TYPE DESCRIPTION:  NA TE	w
PARILITY  ISSUES OBSCRIPTION (5)  NAC USE OF	
210 W Colored " "	1111
B2101504C0 B20930 PDR ADOCK 05000277 PDR PDR PDR (215) 841-5020	