

SEP 18 1990

Howard Young Medical Center  
ATTN: Mr. Ric Johnson, Vice President  
Ancillary Services  
240 Maple Street  
Woodruff, WI 54568

License No. 48-18643-01  
Docket No. 030-13982

Gentlemen:

This refers to the routine safety inspection conducted by Mr. W. P. Reichhold of this office on August 30, 1990, of activities authorized by NRC Byproduct Material License No. 48-18643-01 and to the telephone discussion concerning the inspection results with you on September 7, 1990.


The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

In addition to the above areas, the inspector examined actions described in your letters dated June 30, 1987, and September 15, 1987, regarding apparent violations found during our June 1987, inspection. We have no further questions regarding these matters.

During this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice. A written response is required.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, the enclosures, and your response to this letter will be placed in the NRC Public Document Room.

Sincerely,



George M. McCann, Chief  
Nuclear Materials Safety  
Section 1

Enclosures:

1. Notice of Violation
2. Appendix A Management Control

cc w/enclosures:  
DCD/DCB (RIDS)

RIII

*sum  
9/14/90*

RIII

*sum  
9/14/90*

Reichhold/lh

McCann

9009280146 900913  
REG3 LIC30  
48-18643-01 PDC

111  
JEO7