	LICENSEE EVENT REPORT
	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	MIBRPI 2000-1000000000000000000000000000000000
0 1	REPORT L 6 0 5 0 - 0 1 5 5 0 0 9 0 5 7 8 8 1 0 0 5 7 8 9 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
0 2	While transferring water to the primary system during hot shutdown, the
0 3	condensate storage tank level was below the 65% level specified in
0 4	T/S 11.3.1.4.F.(2) for a period of 70 minutes. The lowest level was 57%.
0 5	The reactor was shut down at the time and no undue hazard existed for this
0 6	incident. Reportable per T/S 6.9.2.b.(2). Incident repetitive. See
0 7	RO-78-26 in letter of 6/30/78.
0 8	
09	SYSTEM CODE CAUSE CAUSE SUBCODE SUBCOD
	TO REPORT TYPE    TO   SEQUENTIAL REPORT NO.   CODE   TYPE
	ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT SUBMITTED FORM SUB. SUPPLIER MANUFACTURER 2 SUPPLIER
1 0	Incident due to operator oversight while attempting to minimize the temper-
1 1	ature differential in the steam drum. The incident will be reviewed with
1 2	all operations personnel, prior to startup from the present plant shutdown,
1 3	to minimize the potential for recurrence.
1 4	
1 5	ACILITY TATUS  SPOWER  OTHER STATUS  OTHER S
	LEASED OF RELEISE AMOUNT OF ACTIVITY (35)  NA LOCATION OF RELEASE (36)
1 7	O O O O O O ST Z O O O O O O O O O O O O O O O O O O
1 8 [	PERSONNEL INJURIES NUMBER DESCRIPTION 41 0 0 0 0 NA
1 9	OSS OF OR DAMAGE TO FACILITY (43)  Z (42) NA
2 0 '5	SUED DESCRIPTION 45 NAC USE ONLY NAC USE ONLY
	68 69 80