

NOTICE OF VIOLATION

Commonwealth Edison Company  
Braidwood Station  
Braceville, Illinois

Docket Nos. 50-456; 50-457  
License Nos. NPF-72; NPF-77

As a result of an inspection conducted on January 8 through February 22, 1994, and in accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (1993), the following violation was identified:

Technical Specification 6.8.1.a requires that applicable procedures referenced in Appendix A of Regulatory Guide 1.33, Revision 2, dated February 1978, shall be established, implemented and maintained. Regulatory Guide 1.33 includes procedures for surveillance tests, liquid radioactive waste effluent collection and discharge, and fire protection program implementation, among others.

Contrary to the above: on February 3, 1994, the licensee failed to properly implement surveillance test procedure, BwHS 4002-062, in that a valve was operated which was not called for in the procedure; on February 4, 1994, the licensee failed to properly implement radioactive waste transfer procedure, BwOP WX-134, in that the wrong tank was aligned for fillup and therefore, overflowed; and on January 29, 1994, the licensee failed to properly implement fire protection procedure, BwAP 1110-3, in that a fire door was blocked open for several minutes with neither a barrier impairment permit nor an attendant.

This is a Severity Level IV violation (Supplement I) (50-456/94005-01(DRP); 50-457/94005-01(DRP)).

The inspection showed that steps had been taken to correct the identified violations and to prevent recurrence. Consequently, no reply to the violation is required and we have no further questions regarding this matter.

Dated at Lisle, Illinois  
this 3<sup>rd</sup> day of March, 1994