## **OPERATING DATA REPORT**

DOCKET NO.
DATE
COMPLETED BY
TELEPHONE

DOCTOBER

50-344

October
10,1978

Gary Bair

503-556-3713

Ext. 234

<b>OPERATI</b>	MIC C	TATE	10
APPEKAII	NE . 3	LAIL	J.S

1. Unit Name: Trojan Nuclear Plant	Notes
2. Reporting Period: September, 1978	
3. Licensed Thermal Power (MWt): 3411	
4. Nameplate Rating (Gross MWe): 1216	2 Comment Comment
5. Design Electrical Rating (Net MWe): 1130	
6. Maximum Dependable Capacity (Gross MWe): 1122	
7. Maximum Dependable Capacity (Net MWe): 1080	
S. If Changes Occur in Capacity Ratings (Items Number 3 Through 7)	Since Last Report, Give Reasons:

9. Power Level To Which Restricted, If Any (Net MWe): 0

10. Reasons For Restrictions, If Any: License action regarding the seismic qualification of the Control Building.

	This Month	Yrto-Date	Cumulative
11. Hours In Reporting Period	720	6551	18239
12. Number Of Hours Reactor Was Critical	0	1803.7	11095.7
13. Keactor Reserve Shutdown Hours	0	0	2162.9
4. Hours Generator Ou-Line	0	1801.1	10540.4
15. Unit Reserve Shutdown Hours	0	0	1508.2
6. Gross Thermal Energy Generated (MWH)	0	5630673	31939219
7. Gross Electrical Energy Generated (MWH)	0	1800580	10450770
8. Net Electrical Energy Generated (MWH)	-3536	1681610	9782324
9. Unit Service Factor	0	27.5	57.8
0. Unit Availability Factor	0	27.5	66.1
1. Unit Capacity Factor (Using MDC Net)	0	23.8	49.7
2. Unit Capacity Factor (Using DER Net)	0	22.7	47.5
3. Unit Forced Outage Rate	0	1.2	12.8

-							
25. 1	If Shut Down At End Of Report Period, Estimated Date of Startup:	Not	Known		7		
	Units In Test Status (Prior to Commercial Operation):		Forecast		A	Chieved	i
	INITIAL CRITICALITY					1. 11. 2	4:5
	INITIAL ELECTRICITY COMMERCIAL OPERATION					4 2	#

24. Shutdowns Scheduled Over Next 6 Months (Type, Date, and Duration of Each):

7810170145 R

(9/77)

# AVERAGE DAILY UNIT POWER LEVEL

DOCKET NO.	50-344
UNIT	Trojan
DATE	October 10, 1978
COMPLETED BY	G. G. Bair
TELEPHONE	503-556-3713
, LUCEI HOILE	Ext. 234

AVERAGE DAILY POWER LEVEL (MWe-Net)	DAY	AVERAGE DAILY POWER LEVEL (MWe-Net)
-3	17	-6
-3	18	-6
-3	19	-6
-4	20	-5
-5	21	
-5	22	-4
-5	23	3
-5	24	-3
-6	25	
	26	
-6	27	-6
-6	28	-5
-6	29	
-2	30	-6
-8	31	NA
-6		

# INSTRUCTIONS

On this format, list the average daily unit power level in MWe-Net for each day in the reporting month. Compute to the nearest whole megawatt.

# UNIT SHUTDOWNS AND POWER REDUCTIONS

50-344 DOCKET NO. Trojan UNIT NAME October 10, 1978 DATE G. G. Bair COMPLETED BY TELEPHONE 503-556-3713 Ext. 234

REPORT MONTH September, 1978

No.,	Date	Type	Duration (Hours)	Reason 2	Method of Shutting Down Reactor?	Licensee Event Report #	System Code <sup>4</sup>	Component Code5	Cause & Corrective Action to Prevent Recurrence	
78-2	780317	5	720	С	1	NA	NA	NA	NA	

F: Forced S: Scheduled Reason:

A-Equipment Failure (Explain) B-Maintenance of Test

C-Refueling

D-Regulatory Restriction E-Operator Training & License Examination

F-Administrative

G-Operational Error (Explain)

H-Other (Explain)

Method:

1-Manual

2-Manual Scram.

3-Automatic Scram.

4-Other (Explain)

Exhibit G - Instructions for Preparation of Data Entry Sheets for Licensee Event Report (LER) File (NUREG-01611

Exhibit 1 - Same Source

(9/77)

Docket No: 50-344
Date: October 10, 1978
Completed by: G. G. Bair
Telephone: 503-556-3713
Ext. 234

## SUMMARY OF OPERATING EXPERIENCE

#### OPERATION:

The month began and ended with the reactor in the cold shutdown condition. The plant startup has been delayed pending license action regarding the seismic qualification of the Control Building structure.

A spurious safety injection signal occurred while at cold shutdown. All required equipment operated as required. The cause appeared to be a noisy pressure transmitter (PT-525) that spiked while a periodic instrumentation test was in progress. The transmitter was replaced. Event date September 5, 1978.

### MAJOR SAFETY-RELATED MAINTENANCE:

Replaced the number 3 seal on RCP C.

#### LICENSE CHANGES:

Amendment 31, LCR-78-03, LCA-46: Changes to the plant organization pattern to divide the Chemistry/Radiation Protection Department into two separate departments and other adjustments, Fig. 6.2-2.

Amendment 32, LCR-77-20, LCA-36: Incorporates surveillance requirements for certain ECCS throttle valves to assure that proper flow resistances are maintained; this prevents total pump flow runout at minimum resistance, provides proper flow split, and acceptable level of total ECCS flow at injection points, Section 3/4 5.2 and 3/4 5.3.

Amendment 33, LCR-78-03, LCA-28: Incorporates changes to permit RCS/RHR pump stop for short time periods at shutdown. Incorporates change to P-7 interlock from turbine impulse pressure to correct initial assumption. Clarifys the requirements for ILRT supplemental verification tests. Makes other minor changes. Table 3.3-1, Table 3.3-4, Fig. 3.4-2, Section 3.4.1.6, 3.4.1.2, 3.6.1.2, 6.7, 6.8.

MISCELLANEOUS: On September 5, four men accidently ingested chlorine gas fumes while work was being done to place the chlorinator in service. All men were examined at hospital; three returned to work on the same day, one returned the next day. Procedure problem and design deficiency were cause of incident.

On September 14 at 0219 a light airplane crashed into three 230 KV supply lines, Allston 1 and 2 and St. Mary's, west of the plant switchyard outside the exclusion area boundary. The crash caused relay action leading to the loss of voltage on H1, A1, and A5 busses. H2 and A2 remained in service from the fourth 230 KV supply line, Rivergate. The west diesel generator being out of service for maintenance was subsequently manually started to energize A1. Normal power was restored the following day.