	LICENSEE EVENT REPORT
	CONTROL BLOCK:
0 1	V A N A S 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 CAT 58
CON'T	REPORT L 6 0 5 0 0 0 3 3 8 7 0 9 2 8 8 1 0 2 4 7 8 9
0 2	An empty snubber fluid reservoir was found on snub: 1-RC-HSS-873. This snubber
0 3	is on reactor coolant piping in C reactor coolant loop cubicle. The health and
0 4	safety of the general public were not affected. This is reportable pursuant t
0 5	T.S. 6.9.1.9.b.
0 6	
0 7	
07	80
0 9	CODE CAUSE CAUSE SUBCODE COMPONENT CODE SUBCODE SUBCOD
	LERIRO EVENT YEAR REPORT NO.  OCCURRENCE REPORT TYPE  NO.  OP 7 O 3 EVENT YEAR REPORT NO.  OCCURRENCE REPORT TYPE  NO.  OP 3 EL O 3  ACTION FUTURE EFFECT SHUTDOWN METHOD HOURS (22) ATTACHMENT SUBMITTED FORM SUB SUPPLIER MANUFACTURER  OCCURRENCE REPORT TYPE  NO.  OP 3 EVENT YEAR REVISION NO.  OP 3 EVENT YEAR REPORT TYPE  NO.  OP 3 EVENT YEAR REPORT TYPE  NO.  OP 3 EVENT YEAR REPORT TYPE  NO.  OP 3 EVENT YEAR REVISION NO.  OP 3 EVENT YEAR REPORT TYPE  NO.  OP 3 EVENT YEAR REVISION NO.  OP 3 EVENT YEAR REPORT TYPE  NO.  OP 3 EVENT YEAR TYPE  NO.  OP 3 EVENT YEAR REPORT TYPE  NO.  OP 3 EVENT YEAR REPORT TYPE  NO.  OP 3 EVENT YEAR REPORT TYPE  NO.  OP 3 EVENT YEAR TYPE  NO.  OP 3 EVENT YEAR TYPE  NO.  OP 4 EVENT YEAR TYPE  NO.  OP
10	A steam generator insulation blanket was laying across the Lexan snubber reservoir.
11	This caused the reservoir to warp and lose fluid. The snubber was replaced and the
<u> </u>	insulation was readjusted to prevent recurrence.
1 3	
1 4 7 8	
1 5	STATUS SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 DISCOV
1 6 R	90
1 7	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)  O O O O O O O O O O O O O O O O O O O
- R	0 0 0 0 0 NA
9	LOSS OF OR DAMAGE TO FACILITY (43)  TYPE DESCRIPTION NA  10  80
10	PUBLICITY NAC USE ONLY ISSUED DESCRIPTION 45 NA 78/0260133