

APPENDIX B

NOTICE OF DEVIATION

Tennessee Valley Authority
Browns Ferry 1, 2, & 3

Docket Nos. 50-259, 260, & 296
License Nos. DPR-33, 52, & 68

Based on the NRC inspection conducted on August 26 - September 25, 1982, certain of your activities appear to deviate from your commitments to the Commission.

Licensee Event Report 259/81-07 dated March 10, 1981, which reported an inoperable fire damper due to paint buildup on a broken fuse link, stated a procedure would be written for inspection and preventive maintenance on all fire dampers.

Contrary to the above, as of September 3, 1982, no procedure had been generated to perform the inspection of fire dampers; however, the licensee has closed out Licensee Event Report 259/81-07 as having been completed.