

50.55(e) Report

RECEIVED
NRC

Arizona Public Service Company

P.O. BOX 21666 • PHOENIX, ARIZONA 85036

December 20, 1982

ANPP-22559-JEC/PSK

1982 DEC 27 PM 12:48

U. S. Nuclear Regulatory Commission
Region V
Creskide Oaks Office Park
1450 Maria Lane - Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. D. M. Sternberg, Chief
Reactor Projects Branch 1

Subject: Interim Report - DER 82-71
A 50.55(e) Potentially Reportable Deficiency Relating to
Henry Pratt MOV Has Loose Bolt Holding Yoke To
Valve Body, In Unit 2 Containment Purge System
File: 82-019-026
D.4.33.2


Reference: Telephone Conversation between T. Young and
G. Duckworth on November 19, 1982

Dear Sir:

The NRC was notified of a potentially reportable deficiency in the
referenced telephone conversation. At that time, it was estimated that a
determination of reportability would be made within thirty (30) days.

Due to the extensive investigation and evaluation required, an Interim
Report is attached. It is now expected that this information will be
finalized by February 4, 1983, at which time a complete report will be
submitted.

Very truly yours,



E. E. Van Brunt, Jr.
APS Vice President
Nuclear Projects Management
ANPP Project Director

EEVBJr/JEC:db

Enclosure

cc: See Attached Page 2

1E27

U. S. Nuclear Regulatory Commission
Attention: Mr. D. M. Sternberg, Chief
Page 2

December 20, 1982
ANPP-22559-JEC/BSK

cc: Richard DeYoung, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

T. G. Woods, Jr.
J. A. Roedel
D. B. Fasnacht
G. C. Andognini
J. R. Bynum
A. C. Rogers
B. S. Kaplan
W. E. Ide
J. Vorees
J. A. Brand
A. C. Gehr
W. J. Stubblefield
W. G. Bingham
R. L. Patterson
R. W. Welcher
R. M. Grant
D. R. Hawkinson
L. E. Vorderbrueggen
G. A. Fiorelli
P. P. Klute

Lynne Bernabei, Esq.
Harmon & Weiss
1725 "I" Street, NW
Washington, D. C. 20006

R. L. Greenfield
Assistant Attorney General
Bataan Memorial Building
Santa Fe, New Mexico 87503

INTERIM REPORT - DER 82-71
POTENTIAL REPORTABLE DEFICIENCY
ARIZONA PUBLIC SERVICE COMPANY (APS)
PVNGS UNIT 2

I. POTENTIAL PROBLEM

During a surveillance inspection of motor operated butterfly valves supplied by Henry Pratt Company, one (1) bolt that secures the yoke to valve body on valve tag number 2JCPBUV3A was not properly tightened. The visual inspection revealed that the lockwasher was not fully compressed. This DER was initiated to evaluate whether this condition could invalidate seismic acceptability.

II. APPROACH TO AND STATUS OF PROPOSED RESOLUTION

Bechtel is currently corresponding with Henry Pratt Company to disposition this item.

III. PROJECTED COMPLETION OF CORRECTIVE ACTION
AND SUBMITTAL OF THE FINAL REPORT

Evaluation of this condition and submittal of the Final Report is forecast to be completed by February 4, 1983.