

APPENDIX A

NOTICE OF VIOLATION

Duke Power Company

License No. CPPR-84

Based on the results of the NRC inspection conducted on August 15-17, 1978, it appears that certain of your activities were not conducted in full compliance with NRC requirements as indicated below. These items have been categorized as described in our correspondence to you dated December 31, 1974.

Criterion V of Appendix B to 10 CFR 50, as implemented by DPC FSAR Section 17, Paragraph 17.1.5 specifies in part that activities affecting quality shall be accomplished in accordance with the requirements imposed by . . . instructions, procedures and drawings. Construction Procedure No. 54, Fire Protection During Cutting and Welding Operations, of the DPC Construction Quality Assurance Program specifies that "Fire watchers shall have fire extinguishers readily available and be trained in its use."

Contrary to the above requirements, on August 16, 1978, the inspector observed that the fire watcher for welding being performed in Unit 2 Reactor Building did not have a fire extinguisher immediately available. The nearest fire extinguisher was located in a congested area approximately 75' from the area in which the welding was being performed.

This is an infraction.

7811080300 Q