

Appendix

NOTICE OF VIOLATION

Sound Expansion Enterprises, Inc.

License No. 48-20224-01

As a result of the inspection conducted on December 14, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violations were identified:

1. License Condition No. 15 requires that your dose calibrator(s) be calibrated in accordance with procedures set forth in Appendix D of Regulatory Guide 10.8, October 1980. The referenced procedures include quarterly test for instrument linearity.

Contrary to the above, no linearity tests have been performed on your dose calibrator since June 21, 1982.

This is a Severity Level V violation (Supplement VI).


2. 10 CFR 35.14(e)(1)(i) requires that your 208 microcurie cesium-137 sealed check source be tested for leakage and/or contamination at intervals not to exceed six months.

Contrary to the above, the referenced source was not leak tested between December 14, 1981 and July 19, 1982, a period in excess of six months.

This is a Severity Level V violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

12-22-82  
Dated

  
D. G. Wiedeman, Chief  
Materials Radiation Protection  
Section 1