

UNITED STATES NUCLEAR REGULATORY COMMISSION WASHINGTON, D. C. 20555

LPDR

November 17, 1982

Docket No. 50-263

50-263

Mr. Allen Short Pioneer Press Energy/Environment 55 East Fourth Street St. Paul, MN 55101

IN RESPONSE REFER TO FOIA-82-514

Dear Mr. Short:

This is in response to your letter dated October 26, 1982, in which you requested, pursuant to the Freedom of Information Act, documents between the NRC and Northern States Power Company concerning the discovery and repair of cracks in recirculation piping at NSP's Monticello nuclear power plant.

Appendix A is a list of documents responsive to your request. You will find these documents enclosed.

This completes NRC's action on your request.

Sincerely,

J. M. Felton, Director Division of Rules and Records Office of Administration

John Philips for

Enclosures: As stated

Re: F0IA-82-514

Appendix A

- 1. Task Interface Agreement, undated.
- 2. PNO-III-82-103, "Recirculation Loop Cap Cracking," September 29, 1982.
- Memo for Darrell G. Eisenhut from R. L. Spessard, "Cracks in Endcap and its Attachment Weld on a Recirculation Loop at Monticello," October 6, 1982.
- 4. Letter to J. G. Keppler, from W. A. Shamla, October 11, 1982.
- Letter to Regional Administrator, from David Musolf, NSP, October 12, 1982.
- 6. IE Bulletin No. 82-03, "Stress Corrosion Cracking in Thick-Wall, Large-Diameter, Stainless Steel, Recirculation System Piping at BWR Plants," October 14, 1982.
- 7. NSP-NRC Meeting Agenda, October 14, 1982.
- 8. Letter to C. E. Larson, NSP, from James G. Keppler, October 19, 1982.
- 9. Letter to J. G. Keppler from W. A. Shamla, October 21, 1982.
- PNO-III-82-103A, "Recirculation Loop Cap Cracking (Update)," October 22, 1982.
- 11. Memo for D. G. Eisenhut, NRR, from R. L. Spessard, "Cracks Found in the Recirculation Loop Piping at Monticello," October 26, 1982.
- 12. Memo for Multiple Addressees from Robert L. Baer, "Task Interface Agreement for Review of ISI Inspections of Thick-Wall, Large Diameter Recirculation System Piping in BWR Plants," October 29, 1982.
- 13. Design Report for Recirculation Line End Cap Repair, Monticello Nuclear Generating Plant," October 22, 1982.