



UNITED STATES  
NUCLEAR REGULATORY COMMISSION

REGION IV  
611 RYAN PLAZA DRIVE, SUITE 400  
ARLINGTON, TEXAS 76011-8064

MAR - 3 1994

MEMORANDUM FOR: L. J. Callan  
Regional Administrator

FROM: Samuel J. Collins  
South Texas Project Restart Panel

SUBJECT: COMPLETION OF SOUTH TEXAS PROJECT UNIT 1 CONFIRMATORY ACTION  
LETTER ITEMS AND RESTART ACTION PLAN STATUS

The purpose of this memorandum is to document the discussions and presentation to you on February 15, 1994, which informed you of the status of Houston Lighting & Power Company's (HL&P) actions to implement the South Texas Project (STP) Confirmatory Action Letter (CAL 4-93-04B) dated October 15, 1993, and the status of tasks associated with the STP Restart Action Plan for Unit 1.

Confirmatory Action Letter

On February 3, 1993, following a reactor trip, the Unit 2 turbine-driven auxiliary feedwater pump started and immediately tripped on overspeed. On February 4, 1993, Unit 1 was required to shut down as a result of repeated failures of the turbine-driven auxiliary feedwater pump to start on demand and operate without tripping on overspeed. As a result of these problems, NRC issued a Confirmatory Action Letter (CAL) to HL&P on February 5, 1993, and dispatched an augmented inspection team (AIT). The CAL required resolution of the overspeed trip condition affecting the turbine-driven auxiliary feedwater pumps and a briefing of NRC staff prior to restart of the unit.

In addition to the AIT activities, several special inspections were conducted at STP, including a diagnostic evaluation by the NRC office of Analysis and Evaluation of Operational Data conducted during the period of March 29 to April 30, 1993. The findings of these reviews resulted in supplements to the CAL issued on May 7, 1993 (CAL 4-93-04), and October 15, 1993 (CAL 4-93-04B). These supplements included issues that NRC considered of sufficient scope and safety significance to require resolution prior to either unit being restarted (Enclosures 1, 2, and 3).

Licensee Actions

In addition to the hardware related issues at STP, the NRC required HL&P to address programmatic problems, including work backlogs, postmaintenance testing shortcomings, outstanding modifications, operations staffing adequacy, fire protection equipment and training, management effectiveness in identifying, pursuing, and correcting plant problems, and the results of internal restart readiness reviews. In response, the licensee developed the

9403150213 940303  
PDR ADOCK 05000498  
P PDR

JED

Operational Readiness Plan submitted to the NRC in August 1993, which described specific actions to be taken prior to the resumption of power operation. Additionally, longer-term actions were described in the Business Plan submitted to NRC in October 1993. HL&P has initiated changes in the STP management from the Group Vice President, Nuclear to the Plant Managers, including a reorganization of the Nuclear Generation department.

On January 29, 1994, HL&P requested a meeting to brief the NRC on the status of the issues described in the February 5, 1993, CAL and its supplements. In the licensee's written submittal they described the actions taken in response to NRC concerns and included a summary of actions remaining prior to resumption of power operation. A public meeting was conducted at the site on February 14, 1994, and a briefing of the STP Restart Panel was conducted by teleconference on February 15, 1994, during which the licensee confirmed actions taken in preparation for the resumption of power operation of STP, Unit 1.

#### NRC Actions

The NRC Region IV Regional Administrator chartered the STP Review Panel on March 11, 1993. The STP Review Panel is composed of regional and program office managers and is to: (1) assure that a consistent approach to issues is being identified at STP and attempt to reach an agency consensus and united approach to addressing the problems at STP; (2) assure that the followup on safety significant issues is being properly coordinated and scheduled; (3) schedule significant meetings and inspections; (4) assure that the views and concerns of different NRC offices are properly addressed; and (5) assure proper coordination for the followup of issues that are identified by the Diagnostic Evaluation Team (DET) inspection.


On April 12, 1993, it was determined that NRC Inspection Manual Chapter 0350, "Staff Guidelines for Restart Approval," was applicable for STP because of its extended shutdown and previous indications of serious deficiencies in licensee management effectiveness. The STP Review Panel assumed the role and responsibilities of the STP Restart Panel and issued the STP Restart Action Plan (Enclosure 4) which includes expected NRC actions required to be taken before restart of the STP Units.

In addition to the focused inspections conducted at STP since the shutdown of Units 1 and 2, an independent Operational Readiness Assessment Team (ORAT) inspection, led by the Special Inspection Branch of the Office of Nuclear Reactor Regulation, was conducted from December 6-10, 1993, and January 12-21, 1994. At the exit meeting conducted on January 21, 1994, the licensee committed to the resolution of issues regarding: (1) configuration management; (2) motor-operated valve opening under system pressure; and (3) surveillance weaknesses. The ORAT concluded that, pending the results of licensee actions concerning the above three items, the ORAT team would be generally supportive of a restart of Unit 1.

Based on the independent inspections and reviews conducted by the NRC staff and described in Enclosure 4 (STP Restart Action Plan), the licensee has satisfactorily completed the items specified in the CAL.

Restart Panel Meeting

The STP Restart Panel met on February 15, 1994, in accordance with NRC Manual Chapter 0350, "Staff Guidelines For Restart Approval," to review outstanding issues requiring resolution prior to restart of Unit 1. Based on the independent inspection and reviews conducted at STP and described in Enclosure 4, the satisfactory resolution of those items addressed in the February 14, 1994, public meeting, and confirmation of the completion of remaining issues on February 15, 1994, the Panel recommended approving the resumption of operation of STP, Unit 1, in accordance with the facility Technical Specifications. In accordance with the February 3, 1994, memorandum from Director, DRP to the STP Restart Panel augmented inspection team coverage of the unit restart will commence about 24 hours prior to entry into Mode 2 operations and will continue until Unit 1 has demonstrated successful operation.

  
Samuel J. Collins, Chairman  
STP Restart Panel

Enclosures:

1. CAL, February 5, 1993
2. CAL, May 7, 1993
3. CAL, October 15, 1993
4. STP Restart Unit 1 Action  
Plan, Revision 4

cc w/enclosures:

Houston Lighting & Power Company  
ATTN: William T. Cottle, Group  
Vice President, Nuclear  
P.O. Box 289  
Wadsworth, Texas 77483

Houston Lighting & Power Company  
ATTN: James J. Sheppard, General Manager  
Nuclear Licensing  
P.O. Box 289  
Wadsworth, Texas 77483

City of Austin  
Electric Utility Department  
ATTN: J. C. Lanier/M. B. Lee  
721 Barton Springs Road  
Austin, Texas 78704

City Public Service Board  
ATTN: K. J. Fiedler/M. T. Hardt  
P.O. Box 1771  
San Antonio, Texas 78296

Newman & Holtzinger, P. C.  
ATTN: Jack R. Newman, Esq.  
1615 L Street, NW  
Washington, D.C. 20036

Central Power and Light Company  
ATTN: G. E. Vaughn/T. M. Puckett  
P.O. Box 2121  
Corpus Christi, Texas 78403

INPO  
Records Center  
700 Galleria Parkway  
Atlanta, Georgia 30339-5957

Mr. Joseph M. Hendrie  
50 Bellport Lane  
Bellport, New York 11713

Bureau of Radiation Control  
State of Texas  
1100 West 49th Street  
Austin, Texas 78756

Judge, Matagorda County  
Matagorda County Courthouse  
1700 Seventh Street  
Bay City, Texas 77414

Licensing Representative  
Houston Lighting & Power Company  
Suite 610  
Three Metro Center  
Bethesda, Maryland 20814



L. J. Callan

-5-

Houston Lighting & Power Company  
ATTN: Rufus S. Scott, Associate  
General Counsel  
P.O. Box 61867  
Houston, Texas 77208

Shaw, Pittman, Potts & Trowbridge  
ATTN: Joseph R. Egan, Esq.  
2300 N Street, N.W.  
Washington, D.C. 20037

E-Mail report to D. Sullivan (DJS)

bcc to DMB (IE01)

bcc distrib. by RIV:

- L. J. Callan
- Branch Chief (DRP/A)
- MIS System
- RIV File
- R. Bachmann, OGC, MS: 15-B-18
- A. Thadani, NRR M/S 8E2
- W. Russell, NRR M/S 12G18
- J. Roe, NRR M/S 13E4
- E. Adensam, NRR M/S 13E4
- RIV OEDO Coordinator, M/S 17G21
- STP Restart Panel Members
- C. Sudman, DRP

Resident Inspector  
 Lisa Shea, RM/ALF, MS: MNBB 4503  
 DRSS-FIPB  
 Project Engineer (DRP/A)  
 Branch Chief (DRP/TSS)

RIV:RPC*	C:DRP/A*	<i>J. for</i> SRV:DRP/A	D:DRP*	D:DRS*
SJCollins:myp	WDJohnson	DPLoveless	ABBeach	TPGwynn
2/ /94	2/ /94	2/2/94	2/ /94	2/ /94

AD:DRSS*	NRR*	NRR*	RIV:RPC	
DDChamberlain	LEKokajko	SCBlack	SJCollins	
2/ /94	2/ /94	2/ /94	2/3/94	

\*previously concurred

E-Mail report to D. Sullivan (DJS)

bcc to DMB (IE01)

bcc distrib. by RIV:

L. J. Callan

Branch Chief (DRP/A)

MIS System

RIV File

R. Bachmann, OGC, MS: 15-B-18

A. Thadani, NRR M/S 8E2

W. Russell, NRR M/S 12G18

J. Roe, NRR M/S 13E4

E. Adensam, NRR M/S 13E4

RIV OEDO Coordinator, M/S 17G21

STP Restart Panel Members

C. Sudman, DRP

Resident Inspector

Lisa Shea, RM/ALF, MS: MNBB 4503

DRSS-FIPB

Project Engineer (DRP/A)

Branch Chief (DRP/TSS)

RIV:RPC*	C:DRP/A*	<i>J. for</i> SRV:DRP/A	D:DRP*	D:DRS*
SJCollins:myp	WDJohnson	DPLoveless	ABBeach	TPGwynn
2/ /94	2/ /94	2/2/94	2/ /94	2/ /94

AD:DRSS*	NRR*	NRR*	RIV:RPC	
DDChamberlain	LEKokajko	SCBlack	SJCollins	
2/ /94	2/ /94	2/ /94	2/3/94	

\*previously concurred

UNITED STATES

## NUCLEAR REGULATORY COMMISSION

REGION IV

611 RYAN PLAZA DRIVE, SUITE 400  
ARLINGTON, TEXAS 76011-8064

FEB - 5 1993

Docket 50-498  
50-499  
License NPF-76  
NPF-80  
CAL 4-93-04Houston Lighting & Power Company  
ATTN: Donald P. Hall, Group  
Vice President, Nuclear  
P.O. Box 1700  
Houston, Texas 77251

SUBJECT: CONFIRMATORY ACTION LETTER

Pursuant to our telephone conversation on February 4, 1993, it is our understanding that South Texas Project, Units 1 and 2, will not be taken critical until you have briefed the NRC staff of the results of your efforts to correct the overspeed trip condition that is affecting the turbine-driven auxiliary feedwater pumps.

Pursuant to Section 182 of the Atomic Energy Act, 42 U.S.C. 2232, and 10 CFR 2.204, you are required to notify me immediately if your understanding differs from that set forth above.

Issuance of this Confirmatory Action Letter does not preclude issuance of an order formalizing the above commitments or requiring other actions on the part of the licensee. Nor does it preclude the NRC from taking enforcement action for violations of NRC requirements that may have prompted the issuance of this letter. In addition, failure to take the actions addressed in this Confirmatory Action Letter may result in enforcement action.

The responses directed by this letter are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Action of 1980, Pub. L. No. 96-511.

CERTIFIED MAIL - RETURN RECEIPT REQUESTED

930260019 3/p.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter will be placed in the NRC Public Document Room.

Sincerely,

  
James L. Milhoan  
Regional Administrator

cc:  
Houston Lighting & Power Company  
ATTN: William J. Jump, Manager  
Nuclear Licensing  
P.O. Box 289  
Wadsworth, Texas 77483

City of Austin  
Electric Utility Department  
ATTN: J. C. Lanier/M. B. Lee  
P.O. Box 1088  
Austin, Texas 78767

City Public Service Board  
ATTN: R. J. Costello/M. T. Hardt  
P.O. Box 1771  
San Antonio, Texas 78296

Newman & Holtzinger, P. C.  
ATTN: Jack R. Newman, Esq.  
1615 L Street, NW  
Washington, D.C. 20036

Central Power and Light Company  
ATTN: D. E. Ward/T. M. Puckett  
P.O. Box 2121  
Corpus Christi, Texas 78403

INPO  
Records Center  
1100 Circle 75 Parkway  
Atlanta, Georgia 30339-3064

Mr. Joseph M. Hendrie  
50 Bellport Lane  
Bellport, New York 11713

Bureau of Radiation Control  
State of Texas  
1101 West 49th Street  
Austin, Texas 78756

Judge, Matagorda County  
Matagorda County Courthouse  
1700 Seventh Street  
Bay City, Texas 77414

Licensing Representative  
Houston Lighting & Power Company  
Suite 610  
Three Metro Center  
Bethesda, Maryland 20814

Houston Lighting & Power Company  
ATTN: Rufus S. Scott, Associate  
General Counsel  
P.O. Box 61867  
Houston, Texas 77208

NRC Public Document Room

Texas Radiation Control Program Director





UNITED STATES  
NUCLEAR REGULATORY COMMISSION

ENCLOSURE 2

REGION IV

511 RYAN PLAZA DRIVE, SUITE 400  
ARLINGTON, TEXAS 76011-8064

MAY - 7 1993

Dockets: 50-498

50-499

Licenses: NPF-76

NPF-80

CAL 4-93-04

Houston Lighting & Power Company  
ATTN: William T. Cottle, Group  
Vice President, Nuclear  
P.O. Box 1700  
Houston, Texas 77251

SUBJECT: CONFIRMATORY ACTION LETTER SUPPLEMENT

This supplements my Confirmatory Action Letter of February 5, 1993, which noted Houston Lighting & Power Company's management agreement that South Texas Project, Units 1 and 2, will not be taken critical until the NRC Staff has been briefed on the results of your efforts to correct the overspeed trip condition which affected the turbine-driven auxiliary feedwater pumps.

Because of the number of issues that have been identified both by your staff and the NRC, you agreed, in our telephone conversation of May 7, 1993, to include the following additional topics in your briefing of the NRC staff which will be scheduled later.

- The Station Problem Report process, including process improvements, thresholds, and the results of your review of existing reports for issues affecting equipment operability and safe plant operation;
- The Service Request backlog, including reduction accomplished during the current outages and your review of outstanding Service Requests for issues affecting equipment operability, safe plant operation, and operator work-arounds;
- The postmaintenance test program, including corrective actions in response to recent violations and other process improvements and the basis for your confidence that equipment removed from service for maintenance is properly restored to an operable status;
- The outstanding design modifications, temporary modifications, and other engineering backlog items, including your review of these for issues affecting equipment operability, safe plant operation, and operator work-arounds;

9305170115 411

- Staffing in the operations department, including adequacy of current staffing levels, plans for replacing planned and unexpected losses to support safe plant startup and operation, and the adequacy of staffing under emergency conditions;
- The status of fire brigade leader training, including verification that this training meets regulatory requirements;
- The status of the fire protection computers, including reliability and functionality of operator interface;
- Management effectiveness in identifying, pursuing, and correcting plant problems, including any plans for independent reviews; and
- The results of your internal restart readiness reviews.

It is important that a thorough review of the backlogs in the areas of Service Requests, engineering items, and Station Problem Reports be conducted to assure that unknown equipment operability problems are identified and corrected. An example of a recent problem affecting safety-related equipment operability which had previously been identified in a Service Request was the missing screws in the Qualified Display Processing System. Weaknesses in the postmaintenance testing program have resulted in inoperable equipment being returned to service. The many outstanding design modifications should be carefully prioritized to ensure that those with importance to safety of operations are implemented in a timely manner and that no potential operability issues exist.

In view of the marginal staffing level in the operations department, it is important that unnecessary burdens and distractions be removed and that you have a plan in place to provide for contingencies and losses. Adequacy of the initial training for fire brigade leaders is an open issue and their overdue requalification training has resulted in an extra burden being placed on nonlicensed operators. Reliability of and operator interface difficulties with the fire protection computers has placed an extra burden on operators and could delay response to a fire in the plant. The outstanding temporary modifications which require additional operator actions, such as manual operation of automatic control systems, should be restored to minimize their impact on the efficiency of operators.

Weaknesses in problem identification, problem reporting, safety impact evaluation, root cause analysis, and corrective action processes have been observed in both the Station Problem Report process and in the Service Request process, indicating ineffective management of these areas.

This listing of topics for discussion is intended to focus the briefing on staff concerns involving potential safety issues. If other such topics are identified prior to the briefing, you will be advised by letter or telephone. Please inform me when your staff has made significant progress in addressing

these issues so I can schedule a special inspection prior to the briefing. All provisions of the February 5, 1993, letter remain in effect. If you have any questions, please feel free to contact me or Bill Beach of my staff.

Sincerely,

*James L. Milhoan*  
James L. Milhoan  
Regional Administrator

cc:  
Houston Lighting & Power Company  
ATTN: William J. Jump, Manager  
Nuclear Licensing  
P.O. Box 299  
Wadsworth, Texas 77483

City of Austin  
Electric Utility Department  
ATTN: J. C. Lanier/M. B. Lee  
P.O. Box 1088  
Austin, Texas 78767

City Public Service Board  
ATTN: R. J. Costello/M. T. Harst  
P.O. Box 1771  
San Antonio, Texas 78296

Newman & Holtzinger, P. C.  
ATTN: Jack R. Newman, Esq.  
1615 L Street, NW  
Washington, D.C. 20036

Central Power and Light Company  
ATTN: D. E. Ward/T. M. Puckett  
P.O. Box 1121  
Corpus Christi, Texas 78403

INPO  
Records Center  
1100 Circle 75 Parkway  
Atlanta, Georgia 30339-3064

Mr. Joseph M. Hendrie  
50 Bellport Lane  
Bellport, New York 11713

Houston Lighting & Power Company -4-

Bureau of Radiation Control  
State of Texas  
1101 West 49th Street  
Austin, Texas 78756

Judge, Matagorda County  
Matagorda County Courthouse  
1700 Seventh Street  
Bay City, Texas 77414

Licensing Representative  
Houston Lighting & Power Company  
Suite 610  
Three Metro Center  
Bethesda, Maryland 20814

Houston Lighting & Power Company  
ATTN: Rufus S. Scott, Associate  
General Counsel  
P.O. Box 51867  
Houston, Texas 77208



UNITED STATES  
NUCLEAR REGULATORY COMMISSION

ENCLOSURE 3

REGION IV

611 RYAN PLAZA DRIVE, SUITE 400  
ARLINGTON, TEXAS 76011-8064

OCT 15 1993

Dockets: 50-498  
50-499  
Licenses: NPF-76  
NPF-80  
CAL 4-93-04B

Houston Lighting & Power Company  
ATTN: William T. Cottle, Group  
Vice President, Nuclear  
P.O. Box 1700  
Houston, Texas 77251

SUBJECT: CONFIRMATORY ACTION LETTER SUPPLEMENT 2

This is the second supplement to my Confirmatory Action Letter of February 5, 1993, which noted Houston Lighting & Power Company's management agreement that South Texas Project, Units 1 and 2, will not be taken critical until the NRC staff has been briefed on the results of your efforts to correct the overspeed trip condition which affected the turbine-driven auxiliary feedwater pumps.

As discussed with Mr. John Groth in a public meeting in Arlington, Texas, on October 5, 1993, the following topics have been identified as additions to the issues which must be resolved prior to startup of either South Texas Project unit. In a telephone conversation on October 15, 1993, you acknowledged these issues and agreed that these topics would be addressed in your briefing of the NRC staff in a meeting to be scheduled prior to unit startup.

The additional topics are:

- Effectiveness of the SPEAKOUT program;
- Standby diesel generator reliability;
- Essential chiller reliability;
- The system certification program;
- Reliability and operability of the feedwater isolation bypass valves;
- Adequacy of tornado damper testing; and
- Acceptability of the emergency preparedness accountability drill results.

These are not new issues, but they were considered to be significant following reviews of the Diagnostic Evaluation Report, your Operational Readiness Program, the allegation process, and recent NRC inspection findings. The complete results of these reviews are documented in NRC Inspection Report 50-498/93-31; 50-499/93-31. This listing of topics for discussion is

CERTIFIED MAIL - RETURN RECEIPT REQUESTED

9310210006-388

intended to focus the briefing on staff concerns involving potential safety issues. If other such topics are identified prior to the briefing, you will be advised by letter or telephone. Please inform me when your staff has made significant progress in addressing these issues so I can schedule special inspections prior to the briefing. All provisions of the February 5, 1993, letter and its supplement of May 7, 1993, remain in effect. If you have any questions, please feel free to contact me or Mr. Art Howell of my staff.

Sincerely,

  
James L. Milhoan  
Regional Administrator

cc:  
Houston Lighting & Power Company  
ATTN: James J. Sheppard, General Manager  
Nuclear Licensing  
P.O. Box 289  
Wadsworth, Texas 77483

City of Austin  
Electric Utility Department  
ATTN: J. C. Lanier/M. B. Lee  
721 Barton Springs Road  
Austin, Texas 78704

City Public Service Board  
ATTN: K. J. Fiedler/M. T. Hardt  
P.O. Box 1771  
San Antonio, Texas 78296

Newman & Holtzinger, P. C.  
ATTN: Jack R. Newman, Esq.  
1615 L Street, NW  
Washington, D.C. 20036

Central Power and Light Company  
ATTN: D. E. Ward/T. M. Puckett  
P.O. Box 2121  
Corpus Christi, Texas 78403

INPO  
Records Center  
700 Galleria Parkway  
Atlanta, Georgia 30339-5957



Bureau of Radiation Control  
State of Texas  
1100 West 49th Street  
Austin, Texas 78756

Judge, Matagorda County  
Matagorda County Courthouse  
1700 Seventh Street  
Bay City, Texas 77414

Licensing Representative  
Houston Lighting & Power Company  
Suite 610  
Three Metro Center  
Bethesda, Maryland 20814

Houston Lighting & Power Company  
ATTN: Rufus S. Scott, Associate  
General Counsel  
P.O. Box 61867  
Houston, Texas 77208



UNITED STATES  
NUCLEAR REGULATORY COMMISSION

ENCLOSURE 4

REGION IV

511 RYAN PLAZA DRIVE, SUITE 400  
ARLINGTON, TEXAS 76011-8064


MAR - 2 1994

MEMORANDUM FOR: L. J. Callan, Regional Administrator  
L. A. Reyes, Acting Associate Director for Projects  
Office of Nuclear Reactor Regulation

FROM: Samuel J. Collins, STP Restart Panel Chairman

SUBJECT: COMPLETION OF SOUTH TEXAS PROJECT UNIT 1 RESTART ACTION PLAN

Attached for your information is Revision 4 of the South Texas Project Restart Action Plan. As noted in the cover memorandum for Revision 0, the Restart Action Plan status has been updated and issued approximately monthly by the Panel. The purpose of this revision is to update the checklists following the completion of the remainder of the checklist items in preparation for restart of STP, Unit 1.

  
Samuel J. Collins  
STP Restart Panel Chairman

Enclosure:  
South Texas Project Unit 1 Restart  
Action Plan - Revision 4

cc w/enclosure:  
Houston Lighting & Power Company  
ATTN: William T. Cottle, Group  
Vice President, Nuclear  
P.O. Box 289  
Wadsworth, Texas 77483

Houston Lighting & Power Company  
ATTN: James J. Sheppard, General Manager  
Nuclear Licensing  
P.O. Box 289  
Wadsworth, Texas 77483

9403140143 3pg.

L. J. Callan  
L. A. Reyes

-2-

City of Austin  
Electric Utility Department  
ATTN: J. C. Lanier/M. B. Lee  
721 Barton Springs Road  
Austin, Texas 78704

City Public Service Board  
ATTN: K. J. Fiedler/M. T. Hardt  
P.O. Box 1771  
San Antonio, Texas 78296

Newman & Holtzinger, P. C.  
ATTN: Jack R. Newman, Esq.  
1615 L Street, NW  
Washington, D.C. 20036

Central Power and Light Company  
ATTN: G. E. Vaughn/T. M. Puckett  
P.O. Box 2121  
Corpus Christi, Texas 78403

INPO  
Records Center  
700 Galleria Parkway  
Atlanta, Georgia 30339-5957

Mr. Joseph M. Hendrie  
50 Bellport Lane  
Bellport, New York 11713

Bureau of Radiation Control  
State of Texas  
1100 West 49th Street  
Austin, Texas 78756

Judge, Matagorda County  
Matagorda County Courthouse  
1700 Seventh Street  
Bay City, Texas 77414

Licensing Representative  
Houston Lighting & Power Company  
Suite 610  
Three Metro Center  
Bethesda, Maryland 20814

L. J. Callan  
L. A. Reyes

-3-

Houston Lighting & Power Company  
ATTN: Rufus S. Scott, Associate  
General Counsel  
P.O. Box 61867  
Houston, Texas 77208

Shaw, Pittman, Potts & Trowbridge  
ATTN: Joseph R. Egan, Esq.  
2300 N Street, N.W.  
Washington, D.C. 20037

SOUTH TEXAS PROJECT UNIT 1 RESTART ACTION PLAN - REVISION 4

A.	<u>GENERAL</u> . . . . .	1
	A.1 PURPOSE . . . . .	1
	A.2 OBJECTIVES . . . . .	1
	A.3 BACKGROUND . . . . .	1
	A.4 RESTART ACTION PLAN OVERVIEW . . . . .	3
B.	<u>PROCESS</u> . . . . .	5
	B.1 INITIAL NRC RESPONSE . . . . .	5
	B.2 NOTIFICATIONS . . . . .	6
	B.3 ESTABLISH AND ORGANIZE THE NRC REVIEW PROCESS . . . . .	7
	B.4 REVIEW IMPLEMENTATION . . . . .	9
	B.5 RESTART AUTHORIZATION . . . . .	13
	B.6 RESTART AUTHORIZATION NOTIFICATION . . . . .	14
C.	<u>ISSUES</u> . . . . .	15
	C.1 ASSESSMENT OF ROOT CAUSE IDENTIFICATION AND CORRECTION . . . . .	15
	C.2 ASSESSMENT OF LICENSEE MANAGEMENT . . . . .	19
	C.3 ASSESSMENT OF PLANT AND CORPORATE STAFF . . . . .	24
	C.4 ASSESSMENT OF PHYSICAL READINESS OF THE PLANT . . . . .	28
	C.5 ASSESSMENT OF COMPLIANCE WITH REGULATORY REQUIREMENTS . . . . .	30
	C.6 COORDINATION WITH INTERESTED AGENCIES/PARTIES . . . . .	31
D.	<u>PLANT SPECIFIC STARTUP ISSUES</u> . . . . .	32
E.	<u>RESTART INSPECTIONS</u> . . . . .	39

9403140147 401A

## A. GENERAL

### A.1 PURPOSE

To provide a basis to plan and coordinate NRC review activities for restart of the South Texas Project units.

### A.2 OBJECTIVES

To ensure that NRC review efforts are consistently developed and implemented, specific guidance is provided to support:

- a. Determining restart issues for review,
- b. Identification of the basic tasks needed to review and approve plant restart, and
- c. Coordination and tracking of restart review activities.

### A.3 BACKGROUND

Both units at STP were shut down in early February 1993. They have remained shut down as a result of numerous broad problems identified by the NRC and the licensee.

On February 3, 1993, following a reactor trip, the Unit 2 turbine-driven auxiliary feedwater pump started and immediately tripped on overspeed. On February 4, 1993, Unit 1 was required to shut down as a result of repeated failures of the turbine-driven auxiliary feedwater pump to start on demand and operate without tripping on overspeed. As a result of these turbine-driven auxiliary feedwater pump problems, NRC issued a Confirmatory Action Letter (CAL) to the Houston Lighting and Power (HL&P) Company on February 5, 1993, and dispatched an augmented inspection team (AIT) to investigate the details surrounding the turbine-driven auxiliary feedwater pump problems. The CAL, and its two supplements, identified a number of issues which required resolution prior to either unit being restarted.

The NRC Region IV Regional Administrator chartered the STP Review Panel on March 11, 1993. The purpose of the STP Review Panel is to:

- Assure consistent approach to issues being identified at South Texas Project and attempt to reach an agency consensus and united approach to addressing the problems at South Texas Project.
- Assure that the followup on safety significant issues is being properly coordinated and scheduled.
- Schedule significant meetings and inspections.
- Assure that the views and concerns of different NRC offices are properly addressed.
- Assure proper coordination for the followup of issues that are identified by the Diagnostic Evaluation Team (DET) inspection.



On April 12, 1993, it was determined that NRC Inspection Manual Chapter 0350, "Staff Guidelines for Restart Approval," was applicable for the South Texas Project Electric Generating Station (STP) because of its extended shutdown and previous indications of serious deficiencies in licensee management effectiveness. The STP Review Panel assumed the role and responsibilities of the STP Restart Panel. These responsibilities include:

1. Reviewing available information related to the plant shutdown
2. Developing the Restart Action Plan
3. Reviewing the licensee's corrective action or improvement program and ensuring that it addresses identified problems and weaknesses
4. Maintaining an ongoing overview of licensee performance
5. Conducting periodic meetings with the licensee to discuss progress toward satisfactory completion of the program
6. Providing oversight and coordination of the NRC's followup activities, reviewing inspection plans and findings, and reviewing licensee performance; identifying areas where NRC inspection and technical review are needed
7. Providing periodic assessments of licensee performance and corrective actions to NRC management
8. Providing a recommendation to the Regional Administrator and the Director of NRR for approval of restart after satisfactory completion of the licensee's restart program

In addition to the AIT activities, several special inspections have been conducted since February 1993, in response to compliance and regulatory issues at STP. Several of these inspections resulted in enforcement action being taken. Corrective actions have been proposed by the licensee.

Additionally, the NRC Office for Analysis and Evaluation of Operational Data conducted a diagnostic evaluation of the STP during the period March 29 to April 30, 1993. The findings of this effort were forwarded to the licensee on June 10, 1993. Numerous items were documented in this report, including a number of issues that NRC considered of sufficient scope and safety significance to require resolution prior to either unit being restarted.

In initial response to the Diagnostic Evaluation Team (DET) report, the licensee submitted a letter on August 5, 1993, and forwarded their Operational Readiness Plan (ORP) on August 28, 1993. In addition to responding to the DET short-term problems that the licensee considered necessary to resolve prior to restart, the ORP addressed the planned actions in response to the CAL, special and routine Regional inspections, and other identified concerns and problems. The ORP addressed initiatives that the licensee considered necessary to be completed prior to the resumption of power operation on either unit. The licensee's Business Plan was issued in October 1993. It describes the initiatives being undertaken to effect sustained performance improvements at the site.

#### A.4 RESTART ACTION PLAN OVERVIEW

A comprehensive NRC review of the restart process is required. The plants are in a safe shutdown condition and measures are in place to physically maintain the plants in a safe shutdown condition. This Restart Action Plan is intended to include expected NRC actions that will be required to be taken before restart of the STP units, including those actions not directly related to the initiating event. The plan defines: the actions which must be accomplished by the NRC, as a minimum, to approve restart; which organization has the lead responsibility for each action; which plant specific issues must be resolved before restart; and who has the actual responsibility for restart approval. The Panel retains responsibility for assessment of the issue and determining whether the issue has been satisfactorily addressed. The STP Restart Panel will make updates and minor revisions to the Restart Action Plan without seeking approval from the Regional Administrator and the Associate Director for Projects. Revisions which are determined by the Panel to be significant will be submitted for approval.

Section B, "PROCESS," of this plan provides generic tasks that support the Restart Action Plan. This section outlines the overall review process needed for the NRC to authorize restart of the facility.

Section C, "ISSUES," contains issues for consideration and areas requiring assessment during the restart review. The issues in this section are broader than the plant specific restart issues and have been determined to be applicable because of the declining performance of the licensee and the extended length of the shutdown. It will not be necessary for each item on the checklists to be assessed, but enough items on a checklist must be reviewed to assess the broader areas such as management oversight and effectiveness.

Section D, "PLANT SPECIFIC STARTUP ISSUES," lists plant-specific issues which must be evaluated and resolved prior to plant startup. This list was developed from a review of the Diagnostic Evaluation Team Report, the Executive Director for Operations staff actions memorandum following the Diagnostic Evaluation, the Confirmatory Action Letter and its supplements, the licensee's Operational Readiness Plan, the allegation review process, and routine and special NRC reports, including the Augmented Inspection. Criteria for selection of restart issues ensured inclusion of issues whose resolution is required to: ensure safe facility operation; comply with Technical Specification and other regulatory requirements; satisfy the plant's design and licensing basis; ensure effective management oversight; or ensure an effective corrective action process. Each of the restart issues is, or will be, included on the licensee's restart issue list. Prior to restarting either STP unit, the licensee will resolve each restart issue to its satisfaction and to the NRC's satisfaction. The licensee will provide a briefing for the NRC staff on the readiness for plant restart, including the issues included in the Confirmatory Action Letter and its supplements prior to restart. This meeting will be open to public observation.

Section E, "RESTART INSPECTIONS," lists the inspections to be completed to evaluate the licensee's response to the startup issues. Issues listed in Sections C and D will be assessed or inspected by resident inspectors, regional inspectors, or an Operations Readiness Assessment Team. In addition, some areas or items may be assessed by the STP Restart Panel.

Each of the checklists in Sections B and C include columns to record the NRC organization with lead responsibility for the item and the date the item was closed. The list in Section D includes a column to record the date the issue was closed. The reference/information notes following each checklist table will document the detailed status of each item, including reference to closeout documentation.

The STP Restart Panel is responsible for implementation of the STP Restart Action Plan. The STP Restart Panel will maintain and periodically review the Restart Action Plan. These actions should: (1) determine review status, (2) verify necessary tasks and items are complete for each phase of the review, and (3) ensure that review tasks and issues for assessment remain consistent with the known facts and status of the restart effort. The generic lists in Sections B and C should be reviewed when significant milestones are completed and prior to restart authorization to ensure any emerging items are considered.

B. PROCESS

B.1 INITIAL NRC RESPONSE:

This section outlines the general NRC restart review process. The major process steps (i.e., Initial Response, Initial Notifications, etc.) are broken down into potential tasks that are provided in a checklist format. The short discussion before each major process step provides insight into the intended activity. An effort was made to place the major steps and tasks in the general order of performance; however, the exact sequence of events cannot be predicted in advance. Thus, many of the major process steps and the specific tasks are expected to be performed in parallel.

The tables provide a column to indicate the lead responsible organization and closeout date. Tasks which the restart panel has determined to not be applicable to the STP restart process are marked "NA."

TASK	RESP ORG	DATE CLOSED
a. Initial notification and NRC management discussion of known facts and issues	RIV	02/04/93
b. Identify/implement additional inspections (i.e., AIT, IIT, or Special)	RIV	02/04/93
c. Determine need for formal regulatory response (i.e., Order or CAL)	RIV	02/05/93
d. Determine need for senior management involvement	RIV, NRR	03/11/93
e. Identify other parties involved, i.e., NRC Organizations, other Federal agencies, and industry organizations	RIV, NRR	02/25/93

Reference Information

B.1.a PN 4-93-003

B.1.b PN 4-93-003; AIT dispatched. AIT Inspection Report 9307 issued on 03/24/93.

B.1.c PN 4-93-003; CAL 4-93-04 issued

B.1.d STP Review Panel Charter approved

B.1.e AEOD was the only other organization involved in the short-term response.

## B.2 NOTIFICATIONS:

Initial notification of the event quickly communicates NRC's understanding of the event and its immediate response to the parties having an interest in the event. Notification to regional and headquarters offices of cognizant Federal agencies may be appropriate. As the review process continues, additional and continuing notifications may be required.

TASK	RESP ORG	DATE CLOSED
a. Issue Daily and Directors Highlight	NRR	02/16/94
b. Issue PN	RIV	02/04/93
c. Conduct Commissioner Assistants' Briefing	RIV	06/25/93
d. Issue Commission Paper	NA	NA
e. Cognizant Federal agencies notified (i.e., FEMA, EPA, DOJ, DOL)	NA	NA
f. State and Local Officials notified	RIV	02/14/94
g. Congressional notification	NA	NA

### Reference/Information

B.2.a Directors Highlight 02/17/93 and approximately weekly thereafter, 02/16/94 notification issued of restart approval.

B.2.b PN 4-93-003

B.2.c Conducted in conjunction with the Commission briefings on the results of the June 93 and January 94 senior managers meetings.

B.2.d NA

B.2.e NA

B.2.f Monthly public meeting announcements. The Deputy Regional Administrator and the STP Restart Panel Chairman briefed the Texas Public Utility Commission and the Austin City Council on 09/09/93. The Governor's office has been kept apprised of events at the South Texas Project through her appointed State Liaison Officer. The Regional State Liaison Officer contacts the Governor's representative when the NRC and STP have public meetings. Additionally, the Governor's representative is mailed or faxed meeting notices, news releases, and inspection reports.

B.2.g PN 4-93-003. NRR discussed with Congressional Affairs.

### B.3 ESTABLISH AND ORGANIZE THE NRC ReVIEW PROCESS:

It will be necessary to establish and organize the NRC restart review to ensure the effective coordination of resources in evaluating the restart process. Effective interfaces within and outside the NRC are critical to properly identify, coordinate, and resolve the pertinent issues. Consider both regional and headquarters offices of cognizant State and Federal agencies.

TASK	RESP ORG	DATE CLOSED
a. Establish the Restart Panel	RIV	03/11/93
b. Assess available information (i.e., inspection results, licensee self-assessments, industry reviews)	PANEL	10/21/93
c. Obtain input from involved parties both within NRC and other Federal agencies, such as FEMA, EPA, DOJ, DOL	PANEL	02/14/94
d. Conduct Regional Administrator Briefing	PANEL	02/93
e. Conduct NRR Executive Team Briefing	NRR	06/93
f. Develop the Case Specific Checklist (CSC)	RIV/DRP	10/21/93
g. Develop the Restart Action Plan	RIV/DRP	10/21/93
h. Regional Administrator approves Restart Action Plan	RIV	10/21/93
i. NRR Associate Director and/or NRR Director approves Restart Action Plan	NRR	10/25/93
j. Implement Restart Action Plan	PANEL	10/25/93
k. Modify CAL/Order as necessary	RIV/DRP	10/15/93

#### Reference/Information

B.3.a First Panel meeting held on 02/25/93. Panel charter approved on 03/11/93.

B.3.b Panel meeting notes of 02/25/93. Restart Action Plan approved 10/21/93.

B.3.c No external issues identified. R. Emch contacted FEMA HQ Marty DiGregory on 12/22/93. No off-site EP issues affect restart. Per C. Hackney, letter from FEMA issued 02/03/94. No congressional interest per Tom Madden 02/01/94. (Reference: L. Kokajko memo to file dated 02/02/94) No DOL or DOJ restart restraints per L. Kokajko 02/01/94. (References: L. Kokajko memos to file dated 02/01/94 and 02/02/94)

B.3.d Briefings provided following Panel meetings.



- B.3.e Full discussion at June 93 and January 94 Senior Managers Meetings. NRR will provide periodic Executive Team briefings.
- B.3.f This document includes the CSC.
- B.3.g This document is the Restart Action Plan.
- B.3.h Restart Action Plan approved by Regional Administrator 10/21/93.
- B.3.i Restart Action Plan approved by NRR Associate Director 10/25/93.
- B.3.j Restart Action Plan implementation in progress 10/25/93.
- B.3.k CAL Supplement issued May 7, 1993. CAL Supplement 2 issued on October 15, 1993.

#### B.4 REVIEW IMPLEMENTATION:

The review can be accomplished by a variety of methods including inspections, testing, evaluation of licensee self-assessments, evaluation of licensee action plans, and regulatory actions (i.e., Orders, CAL's). Early establishment of the review areas will assist in defining the methods to perform the review. Once the licensee has developed its corrective action plan, the NRC shall review that plan to verify its completeness and adequacy. The NRC will also need to determine which corrective actions will be required to be implemented before restart and, thus, become restart issues which can be deferred to some later date as long-term corrective actions. The discussions and issues provided in Section C of this appendix provide additional information to support the review activities described below.

##### B.4.1 Root Causes and Corrective Actions:

TASK	RESP ORG	DATE CLOSED
a. Evaluate findings of AIT, IIT, or Special Team Inspection	RIV	03/24/93
b. Licensee performs root cause analysis and develops corrective action plan for root causes	PANEL	10/15/93
c. NRC evaluates licensee's root cause determination and corrective action plan	PANEL	11/18/93

##### Reference/Information

B.4.1.a AIT IR 9331, AIT Followup IR 9305 dated 04/08/93.

B.4.1.b DET response status letter submitted 08/05/93. Operational Readiness Plan submitted 08/28/93. Business Plan submitted 10/15/93. ORP clarification submitted 12/31/93.

B.4.1.c NRC letters of 08/26/93 and 09/22/93 acknowledged receipt of licensee submittals of 08/05/93 and 08/28/93. NRC letter of 11/18/93 acknowledged receipt of Business Plan.

##### B.4.2 Assessment of Equipment Damage:

This section is not applicable for the South Texas Project restart approval.

### B.4.3 Determine Restart Issues and Resolution:

The establishment of the restart issues that require resolution before restart demands a clear understanding of the issues and the actions required to address those issues by both the NRC and the licensee. This table outlines steps to determine the restart issues and NRC's evaluation of their resolution.

TASK	RESP ORG	DATE CLOSED
a. Review/evaluate licensee generated restart issues	PANEL	10/05/93
b. Independent NRC identification of restart issues (consider sources external to NRC and licensee)	PANEL	09/27/93
c. NRC/licensee agreement on restart issues	PANEL	10/15/93
d. Evaluate licensee's restart issues implementation process	PANEL	02/01/94
e. Evaluate licensee's implementation verification process	PANEL	02/01/94

#### Reference/Information

- B.4.3.a Public meeting and Panel meeting.
- B.4.3.b Panel meeting notes. IR 9331
- B.4.3.c CAL Supplement 2 issued. Lists compared in IR 9333.
- B.4.3.d Refer to IR 9331 and subsequent reports. Panel discussion 02/01/94.
- B.4.3.e Line management assessment and independent assessment processes reviewed in IRs 9333, 9343, and 9354. Addressed in ORAT inspection. Discussed in Panel meeting 02/01/94.

B.4.4 Obtain Comments:

Since some shutdowns involve a broad number of issues, solicitation of comments from diverse sources may be appropriate. The decision to solicit comments from a group and the level of participation should be made on a case-by-case basis. Input from these groups should be factored into the restart process when they contribute positively to the review. Note: If needed, comments concerning the adequacy of state and local emergency planning and preparedness must be obtained from FEMA headquarters through NRR.

TASK	RESP ORG	DATE CLOSED
a. Obtain public comments	PANEL	02/14/94
b. Obtain comments from State and Local Officials	PANEL	02/14/94
c. Obtain comments from applicable Federal agencies	PANEL/NRR	NA

Reference/Information

- B.4.4.a DET public exit meeting at site 06/03/93. Public meetings at site 07/16/93 and 09/08/93. Public meeting in the RIV office 10/05/93. Public meetings at site 10/29/93, 12/02/93, and 01/07/94. ORAT exit meeting on 01/21/94 was open for public observation. Public meeting at site 02/14/94.
- B.4.4.b The Deputy Regional Administrator and the STP Restart Panel Chairman briefed the Texas Public Utility Commission and the Austin City Council on 09/09/93. City of Austin representatives met with the Restart Panel Chairman on 11/16/93. The Governor's office has been kept apprised of events at the South Texas Project through her appointed State Liaison Officer. The Regional State Liaison Officer contacts the Governor's representative when the NRC and STP have public meetings. Additionally, the Governor's representative is mailed or faxed meeting notices, news releases, and inspection reports.
- B.4.4.c Not needed for implementation review.

B.4.5 Closeout Actions:

When the actions to resolve the restart issues and significant concerns are substantially complete, closeout actions are needed to verify that planned inspections and verifications are complete. The licensee should certify that corrective actions required prior to restart are complete and that the plant is physically ready for restart. This table provides actions associated with completion of significant NRC reviews and preparations for restart.

TASK	RESP ORG	DATE CLOSED
a. Evaluate licensee's restart readiness self-assessment	PANEL	02/15/94
b. NRC evaluation of applicable items from section C "ISSUES" complete	PANEL	02/15/94
c. Restart issues closed	PANEL	02/15/94
d. Conduct NRC Restart Readiness Team Inspection	NRR	01/21/94
e. Issue Augmented Restart Coverage Inspection Plan	RIV/DRP	02/01/94
f. Comments from other parties considered	PANEL	02/14/94
g. Determine that all conditions of the CAL and its Supplements are satisfied	PANEL	02/15/94
h. Re-review of Generic Restart Checklist complete	PANEL	02/15/94

Reference/Information

- B.4.5.a Discussed in IRs 9333, 9343, and 9354. Addressed in ORAT inspection. Discussed in panel meeting 2/15/94.
- B.4.5.b Panel meeting 02/15/94.
- B.4.5.c Refer to Section D for status of the restart issues.
- B.4.5.d ORAT inspection completed and public exit held.
- B.4.5.e Draft plan presented to Panel members 02/01/94.
- B.4.5.f 02/14/94 Public Meeting.
- B.4.5.g 02/14/94 Public meeting, 02/15/94 Panel Meeting
- B.4.5.h 02/14/94 Public meeting, 02/15/94 Panel Meeting

B.5 RESTART AUTHORIZATION:

When the restart review process has reached the point that the issues have been identified, corrected, and reviewed, a restart authorization process is begun. At this point the restart panel should confirm that all actions are substantially complete and that the panel has not overlooked any items.

TASK	RESP ORG	DATE CLOSED
a. Prepare restart authorization document and basis for restart	PANEL CHAIRMAN	02/15/94
b. NRC Restart Panel approves Restart Authorization	PANEL	02/15/94
c. No restart objections from other applicable HQ offices	NRR	02/15/94
d. No restart objections from applicable Federal agencies	PANEL	02/15/94
e. Regional Administrator concurs in Restart Authorization	RIV	02/15/94
f. NRR Associate Director and/or NRR Director Concurs in Restart Authorization	NRR	02/14/94
g. EDO concurs in Restart Authorization	RIV/RA	02/14/94
h. Conduct ACRS briefing/notification	NRR	NA
i. Conduct Commission briefing/notification	NA	02/17/94
j. Commission concurs in Restart Authorization	NA	NA
k. Regional Administrator authorizes restart	RIV	02/15/94

Reference/Information

- B.5.a CAL letter to HL&P 02/15/94.
- B.5.b 02/14/94 Public Meeting and 02/15/94 Panel Meeting.
- B.5.c 02/14/94 Public Meeting and 02/15/94 Panel Meeting.
- B.5.d On 12/22/93 Richard Emch discussed STP with FEMA HQ Marty DiGregory. No off-site EP issues affect STP restart. Letter from FEMA 02/03/94. No congressional interest per Tom Madden 02/01/94. No DOL or DOJ restart restraints per L. Kokajko 02/01/94.
- B.5.e 02/15/94 CAL letter.
- B.5.f RIV RA briefing of D/EDO and DD/NRR on 02/14/94.
- B.5.g RIV RA briefing of D/EDO and DD/NRR on 02/14/94.
- B.5.h Preliminary ACRS staff notification made by M. Virgilio to J. Larkins 05/08/93. Not required prior to restart. Briefing will be provided after restart if requested.
- B.5.i Not required prior to restart but was accomplished during 1/27/94 operating reactors briefing. Commission briefing paper also provided on 02/17/94.
- B.5.j NA
- B.5.k 02/15/94 CAL letter.

B.6 RESTART AUTHORIZATION NOTIFICATION:

Notify the applicable parties of the restart authorization. Communication of planned actions is important at this stage to ensure that NRC intentions are clearly understood.

TASK	RESP ORG	DATE CLOSED
a. Commission	NRR	02/17/94
b. EDO	RIV/NRR	02/14/94
c. Congressional Affairs	NRR	02/14/94
d. ACRS	NRR	NA
e. Applicable Federal Agencies	RIV/NRR	02/15/94
f. Public Affairs	RIV	02/14/94
g. State and Local Officials	RIV	02/14/94

Reference/Information

- B.6.a Commissioners Assistants briefed by NRR 02/14/94. Briefing paper issued 02/17/94.
- B.6.b Briefing conducted 02/14/94.
- B.6.c Congressional Affairs briefed by NRR 02/14/94.
- B.6.d Not required prior to restart. Briefing will be provided after restart if requested.
- B.6.e See B.3.c.
- B.6.f Attended 2/14/94 CAL meeting.
- B.6.g SLO notifications completed on 02/14/94 and public meetings held. See B.2.f.

C. ISSUES

C.2 ASSESSMENT OF ROOT CAUSE IDENTIFICATION AND CORRECTION:

C.1.1 ROOT CAUSE ASSESSMENT:

The root cause(s) of the event or the conditions requiring the shutdown should be identified and corrected. A comprehensive licensee corrective action plan should be developed that addresses the root cause(s) and all applicable issues including corrective action, implementation, and verification. The corrective action plan should also include sufficient measures to prevent recurrence of problems. The NRC shall review the licensee's corrective action plan to verify its completeness and adequacy and to determine which corrective actions will be required to be implemented before restart and which can be deferred to some later date as long-term corrective actions.

The NRC staff will review the licensee's corrective action activities and use the appropriate tools available in the regulatory program to determine the acceptability of these actions with respect to safe operations. The tools which are available include: staff reviews; the systematic assessment of licensee performance (SALP); inspections, including special team inspections; requests under 10 CFR 50.54(f); senior management meetings; enforcement conferences; and a restart panel. The results of the staff's reviews will be documented by safety evaluations, license amendments, orders, Confirmatory Action Letters, inspection reports, Commission meeting transcripts, and enforcement documents.

ISSUES	RESP ORG	DATE CLOSED
1. Conditions requiring the shutdown are clearly understood	RIV	02/05/93
2. Root causes of the conditions requiring the shutdown are clearly understood	PANEL	06/10/93
3. Root causes of other significant problems are clearly understood	PANEL	06/10/93
4. Evaluate adequacy of the root cause analysis program	RIV NRR/DRIL	02/01/94

Reference/Information

1. CAL of 02/05/93; CAL Supplements of 05/07/93 and 10/15/93; DET Report of 06/10/93
2. CAL of 02/05/93; CAL Supplements of 05/07/93 and 10/15/93; DET Report of 06/10/93. TDAFW issues discussed in IR 9338.
3. CAL of 02/05/93; CAL Supplements of 05/07/93 and 10/15/93; DET Report of 06/10/93
4. Favorable findings in IR 9343. Significant improvements noted in IR 9354. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.



Weaknesses were noted but improvements were in progress. Discussed in Panel meeting 02/01/94.

C.1.2 DAMAGE ASSESSMENT:

Not applicable for South Texas Project.

C.1.3 CORRECTIVE ACTIONS:

ISSUES	RESP ORG	DATE CLOSED
1. Evaluate adequacy of the comprehensive corrective action plan	PANEL	11/18/93
2. Evaluate adequacy of the corrective action programs for specific root causes	RIV NRR/DRIL	02/01/94
3. Assess control of corrective action item tracking	RIV NRR/DRIL	01/27/94
4. Effective corrective actions for the conditions requiring the shutdown have been implemented	RIV NRR/DRIL	02/15/94
5. Effective corrective actions for other significant problems have been implemented	RIV NRR/DRIL	02/15/94
6. Adequacy of the licensee's corrective action verification process	RIV NRR/DRIL	01/27/94

Reference/Information

1. DET response status letter submitted 08/05/93. Operational Readiness Plan submitted 08/28/93. Business Plan submitted 10/15/93. NRC letters of 08/26/93 and 09/22/93 acknowledged receipt of licensee submittals of 08/05/93 and 08/28/93. NRC letter of 11/18/93 acknowledged receipt of Business Plan.
2. IR 9338 addressed auxiliary feedwater. Other issues addressed in IRs 9344, 9354, and 9345. ORAT input on adequacy was discussed in 01/27/94 Panel meeting. Discussed in Panel meeting 02/01/94.
3. IR 9333 found that appropriate mechanisms were in place to control SPR backlogs and manage new incoming SPRs. SPR backlog noted in IR 9343. Updated in IR 9354. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
4. IR 9338 addressed root causes for TDAFW pump issues. ORAT input on adequacy was discussed in 01/27/94 Panel meeting. Panel meeting 02/15/94. IR 94-09.

5. Addressed in IRs 9335, 9344, 9345, and 9354. ORAT input on adequacy was discussed in 01/27/94 Panel meeting. Discussed in Panel meeting 02/01/94.
6. Addressed in IR 9354. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.

C.1.4 SELF-ASSESSMENT CAPABILITY:

The occurrence of an event may be indicative of potential weaknesses in the licensee's self-assessment capability. A strong self-assessment capability creates an environment where problems are readily identified, prioritized, and tracked. Effective corrective actions require problem root cause identification, solutions to correct the cause, and verification methods that ensure the issue is resolved. Senior licensee management involvement in self-assessment is treated separately.

ISSUES	RESP ORG	DATE CLOSED
1. Effectiveness of Quality Assurance Program	RIV/DRS	12/14/93
2. Adequacy of Industry Experience Review Program	RIV/DRS	01/27/94
3. Adequacy of licensee's Independent Review Groups	RIV/DRS	12/14/93
4. Adequacy of deficiency reporting system	RIV NRR/DRIL	01/27/94
5. Staff willingness to raise concerns	RIV/DRS	02/01/94
6. Effectiveness of PRA usage	NA	NA
7. Adequacy of Commitment Tracking Program	NA	NA
8. External audit (i.e., INPO) capability	PANEL	02/01/94
9. Quality of 10 CFR 50.72 and 50.73 Reports	NA	NA

Reference Information

1. Program adequacy noted in IR 9343.
2. Program adequacy noted in IR 9343. ORAT input on adequacy was discussed in 01/27/94 Panel meeting. Addressed for Diesel generators in IR 9344. Weaknesses noted in IR 9407.
3. Review group adequacy noted in IR 9343. Independent assessment addressed in IR 9406.
4. Addressed in IRs 9343 and 9354. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
5. Addressed in IR 9352. ORAT input on adequacy was discussed in 01/27/94 Panel meeting. Discussed in Panel meeting 02/01/94. Licensee CAL letter 01/29/94.
6. NRC review of licensee's PSA completed 08/31/93.
7. NA

8. INPO review/assistance visit completed 09/24/93. Other independent reviews have been conducted in the areas of security management, standby diesel generators, employee concerns program, and operational readiness. Panel meeting 02/01/94.
9. NA

## C.2 ASSESSMENT OF LICENSEE MANAGEMENT:

The licensee's management organization should be assessed by NRC staff to ensure that qualified personnel, the proper environment, and resources are provided to ensure that the problems and their root causes have been or are being rectified. The organization must demonstrate that it can coordinate, integrate, and communicate its objectives so that they are assigned appropriate priorities regarding safety significance and are completed in a timely manner. NRC reviews will determine if the licensee has effective corporate management oversight and involvement in plant operations and problem resolution.

The licensee's management must appreciate the safety significance of certain issues and ensure that these issues are resolved. The licensee's organization should: (1) exhibit good teamwork among its subelements; (2) provide strong engineering and technical support for plant activities; (3) possess the internal ability to recognize safety problems, develop and implement adequate corrective actions and verify their effectiveness; (4) possess an independent self-assessment capability that can identify and correct performance problems; and (5) have adequate administrative and technical resources available to accomplish the stated goals and objectives.

C.2.1 Management Oversight and Effectiveness

ISSUES	RESP ORG	DATE CLOSED
1. Management commitment to achieving improved performance	PANEL NRR/DRIL	01/27/94
2. Performance goals/expectations developed for the staff	PANEL NRR/DRIL	01/27/94
3. Goals/expectations communicated to the staff	PANEL NRR/DRIL	01/27/94
4. Resources available to management to achieve goals	PANEL NRR/DRIL	01/27/94
5. Qualification and training of management	PANEL NRR/DRIL	01/27/94
6. Management's commitment to procedure adherence	PANEL NRR/DRIL	01/27/94
7. Management involvement in self-assessment and independent self-assessment capability	PANEL NRR/DRIL	01/27/94
8. Effectiveness of management review committees	PANEL NRR/DRIL	01/27/94
9. Effectiveness of internal management meetings	PANEL NRR/DRIL	01/27/94
10. Management in-plant time	PANEL NRR/DRIL	01/27/94
11. Management's awareness of day-to-day operational concerns	PANEL NRR/DRIL	01/27/94
12. Ability to identify and prioritize significant issues	PANEL NRR/DRIL	01/27/94
13. Ability to coordinate resolution of significant issues	PANEL NRR/DRIL	01/27/94
14. Ability to implement effective corrective actions	PANEL NRR/DRIL	01/27/94

### Reference/Information

1. Favorable general comments in IR 9343. Other restart inspections noted good management response to correcting problems related to the restart issues. Favorable comments in IR 9354. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
2. Favorable comments in IR 9343. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
3. Favorable comments in IR 9343. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
4. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
5. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
6. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
7. Favorable comments in IR 9343. Addressed in IR 9406. Addressed in public meetings. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
8. Favorable comments in IR 9343. Addressed in IR 9406. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
9. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
10. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
11. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
12. Favorable comments in IR 9343 and 9354. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
13. Favorable comments in IR 9343. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
14. Favorable comments in IR 9343 and 9354. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.

C.2.2 Management Organization and Support:

ISSUES	RESP ORG	DATE CLOSED
1. Structure of the organization	PANEL	01/27/94
2. Ability to adequately staff the organization	RIV/DRS	01/27/94
3. Effect of any management reorganization	PANEL	01/27/94
4. Establishment of proper work environment	RIV NRR/DRIL	01/27/94
5. Ability to foster teamwork among the staff	RIV NRR/DRIL	01/27/94
6. Ability to resolve employee concerns	RIV/DRS	01/27/94
7. Ability to provide engineering support	RIV/DRS NRR/DRIL	01/27/94
8. Adequacy of plant administrative procedures (SPR, PMT, Work Control, ECO)	RIV/DRP/DRS	01/27/94
9. Information exchange with other utilities	RIV/DRS	01/27/94
10. Participation in industry groups	RIV/DRS	12/14/93
11. Ability to function in the emergency response organization	RIV/DRSS	12/08/93
12. Coordination with offsite emergency planning officials	NA	NA

Reference/Information

1. IR 9341 addressed operations and maintenance. IR 9345 addressed engineering. Reorganization addressed in several public meetings. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
2. IR 9341 addressed operations and maintenance. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
3. IR 9347 addressed effect on Emergency Preparedness. IR 9341 addressed operations and maintenance. IR 9345 addressed engineering. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
4. Favorable findings for operations department noted in IR 9341. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
5. Favorable comments in IR 9343. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
6. Addressed in IR 9352. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
7. Good support for operations noted in IR 9341. Addressed in IR 9345. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
8. Work control process addressed in IRs 9353 and 9345. Weakness noted in IR 9354. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.

9. Addressed in IR 9343. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
10. Addressed in IR 9343. IR 9344 noted active support of Cooper-Bessemer Owners Group.
11. IR 9347.
12. NA



### C.3 ASSESSMENT OF PLANT AND CORPORATE STAFF:

The licensee staff must be capable of recognizing and carrying out their responsibilities to ensure public health and safety. An adequate number of fully qualified licensee staff shall be assigned. A proactive attitude toward safety issues should be demonstrated in all aspects of operations. In this regard, the licensee staff should display attentiveness to duty, fitness for duty, a disciplined approach to activities, a sensitivity for trends in the plant, security awareness, an openness of communications, and a desire for teamwork that supports effective relations between different groups (e.g., management, operations, health physics, maintenance, engineering, security, and contractors).

#### C.3.1 Assessment of Staff:

ISSUES	RESP ORG	DATE CLOSED
1. Staff commitment to achieving improved performance	PANEL NRR/DRIL	01/27/94
2. Staff's safety consciousness	PANEL NRR/DRIL	01/27/94
3. Understanding of management's expectations/goals	PANEL NRR/DRIL	01/27/94
4. Understanding of plant issues and corrective actions	PANEL NRR/DRIL	01/27/94
5. Morale	PANEL NRR/DRIL	01/27/94
6. Staff (union)/management relationship	NA	NA
7. Structure of the organization	PANEL NRR/DRIL	01/27/94
8. Effect on the staff of any reorganization	PANEL NRR/DRIL	01/27/94
9. Resources available to the staff	PANEL NRR/DRIL	01/27/94
10. Qualifications and training of the staff	PANEL NRR/DRIL	01/27/94
11. Staff's work environment	PANEL NRR/DRIL	01/27/94
12. Staff's fitness for duty	NA	NA
13. Attentiveness to duty	PANEL NRR/DRIL	01/27/94
14. Level of attention to detail	PANEL NRR/DRIL	01/27/94

15. Adequacy of staffing	PANEL NRR/DRIL	01/27/94
16. Off-hour plant staffing	PANEL NRR/DRIL	01/27/94
17. Rotation schedule for shift workers	PANEL NRR/DRIL	01/27/94
18. Staff overtime usage	PANEL NRR/DRIL	01/27/94
19. Amount of contractor usage	PANEL NRR/DRIL	01/27/94
20. Staff/contractor relationship	PANEL	02/01/94
21. Understanding of the allegation process and protection of workers who communicate with the NRC	RIV/DRS	02/01/94
22. Procedure usage/adherence	RIV/DRP	01/27/94
23. Awareness of plant security	RIV/DRSS	09/01/93
24. Understanding of offsite emergency planning issues	NA	NA

Reference/Information

1. Favorable comments in IR 9343. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
2. Favorable comments in IR 9343. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
3. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
4. SDG problems handled well per IR 9336. Addressed in IR 9354. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
5. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
6. NA
7. Unitization addressed in IR 9341. Engineering addressed in IR 9345. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
8. Unitization addressed in IR 9341. Engineering addressed in IR 9345. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
9. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
10. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
11. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
12. NA
13. Favorable comments in IR 9345. Weakness noted in IR 9354. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
14. Weakness noted in IR 9354. Favorable comments in IR 9345. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
15. Operations and maintenance addressed in IR 9341. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
16. Off-hour engineering support to operations and maintenance addressed in IR 9341. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.

17. Six shift rotation addressed in IR 9406. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
18. Operator overtime addressed in IR 9406. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
19. Current status and ORAT input were discussed in 01/27/94 Panel meeting.
20. Weaknesses in control of motor operated valve contractor addressed in IR 9345. Addressed in 01/07/94 public meeting. Discussed in Panel meeting 02/01/94.
21. Addressed in IR 9352. Discussed in Panel meeting 02/01/94.
22. Good procedure adherence noted in IRs 9330 and 9341. Mixed observations in IR 9345. Weakness noted in IR 9354. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
23. STP Security force management initiatives and the results of an independent security force management assessment were discussed in a management meeting with the licensee on September 1, 1993. No restart issues were identified as a result of this meeting or previous security inspection findings.
24. No restart issues have been identified in this area.

C.3.2 Assessment of Corporate Support:

Not Applicable for South Texas Project.

C.3.3 Operator Issues:

ISSUES	RESP ORG	DATE CLOSED
1. Licensed operator staffing meets requirements and licensee goals	RIV/DRS NRR/DRIL	01/27/94
2. Level of formality in the control room	RIV/DRS NRR/DRIL	01/27/94
3. Adequacy of control room simulator training	RIV/DRS NRR/DRIL	11/02/93
4. Control room/plant operator awareness of equipment status	RIV/DRS NRR/DRIL	01/27/94
5. Adequacy of plant operating procedures	RIV/DRS NRR/DRIL	01/27/94
6. Procedure usage/adherence	RIV/DRS NRR/DRIL	01/27/94
7. Log keeping practices	NA	NA

Reference/Information

1. IR 9341. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
2. Favorable observations in IR 9330. Generally effective communications and command and control noted, with exceptions, in IR 9334. Mixed observations in IR 9336. Significant improvement noted in IR 9345. ORAT input on adequacy was discussed in 01/27/94 Panel meeting. ORAT input was very favorable.
3. Results of 09/27/93 - 10/01/93 exams (IR 93-34)
4. Favorable observations in IR 9330. Good response to SFP level decrease noted in IR 9336. Operator weaknesses contributed to RCS overfill in IR 9336. Favorable observations in IRs 9341 and 9345. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
5. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
6. Some favorable observations in IR 9330, but equipment clearance order problems noted in IRs 9330 and 9336. Favorable observations in IR 9341. Weakness noted in IRs 9345 and 9354. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
7. No restart issues have been identified in this area. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.

#### C.4 ASSESSMENT OF PHYSICAL READINESS OF THE PLANT:

The physical condition of the plant is of principal importance not only when a shutdown is the result of a physical event or a hardware deficiency but for other reasons as well, especially following prolonged outages.

The causes of significant equipment problems should be identified and appropriate corrective actions taken. Operational testing should verify that each significant equipment problem has been resolved. As appropriate, the complete spectrum of preoperational and startup testing programs may need to be expanded to cover the more complex types of problems or the effects on plants that have been shut down for extended periods.

The licensee must be able to demonstrate that all needed safety equipment is operational before restart. Systems and equipment need to be available and aligned. Surveillance tests should also be up to date. The maintenance backlog should be managed at controllable levels and should be evaluated for impact on safe operation. Maintenance must also be capable of responding to equipment failures during startup and operation and should not be hindered by unresolved chronic problems with equipment readiness. Procedures should be adequate and up to date. The emergency preparedness function both onsite and offsite needs to be capable of protecting public health and safety.

ISSUES	RESP ORG	DATE CLOSED
1. Operability of technical specifications systems	RIV/DRP NRR/DRIL	01/27/94
2. Operability of required secondary and support systems	RIV/DRP NRR/DRIL	01/27/94
3. Results of prestartup testing	RIV/DRP	02/01/94
4. Adequacy of system lineups	RIV/DRP NRR/DRIL	01/27/94
5. Adequacy of surveillance tests/test program	RIV/DRP NRR/DRIL	01/27/94
6. Significant hardware issues resolved (i.e., damaged equipment, equipment ageing, modifications)	PANEL	02/01/94
7. Adequacy of the power ascension testing program	PANEL	02/15/94
8. Adequacy of plant maintenance program effectiveness	RIV/DRS NRR/DRIL	02/01/94
9. Maintenance backlog managed and impact on operation assessed	RIV/DRS	02/01/94
10. Adequacy of plant housekeeping and equipment storage	RIV/DRP	01/27/94
11. Adequacy of emergency preparedness accountability drills	RIV/DRSS	12/08/93

#### Reference/Information

1. ORAT input on adequacy was discussed in 01/27/94 Panel meeting. Walkdowns did not identify system lineup problems.
2. Fire protection system improvements noted in IR 9337. Deferred maintenance on non-certified systems addressed in IR 9353. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
3. Postmaintenance and postmodification testing addressed in IRs 9338, 9339, 9342, 9344, 9335, 9346, 9354, 9404, 9355. Discussed in Panel meeting 02/01/94.
4. ORAT input on adequacy was discussed in 01/27/94 Panel meeting. ORAT system walkdowns found systems were properly aligned.
5. Addressed in IRs 9345 and 9346. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
6. TDAFW issues addressed in IR 9338. Other issues addressed in IRs 9335, 9344, 9345, 9354, 9406, and 9409. Discussed in Panel meeting 02/01/94.
7. DRP review completed 9409. Inspection coverage per 02/03/94 DRP memo. Panel meeting 02/15/94.
8. Favorable comments in IR 9353. ORAT input on adequacy was discussed in 01/27/94 Panel meeting. Discussed in Panel meeting 02/01/94.

9. Progress noted in IR 9353. Addressed in IR 9408. Discussed in Panel meeting 02/01/94.
10. Improvement noted in IRs 9336 and 9337. Material condition improvement noted in IR 9353. Significant improvement noted in IR 9345. ORAT input on adequacy was discussed in 01/27/94 Panel meeting.
11. Addressed in IR 9347.

C.5 ASSESSMENT OF COMPLIANCE WITH REGULATORY REQUIREMENTS:

The plant and its prospective operation must not be in conflict with any applicable regulations or requirements of any document authorizing restart (such as license amendments, orders, or a CAL). Restart should not conflict with any ongoing matter such as an Atomic Safety and Licensing Board hearing.

ISSUES	RESP ORG	DATE CLOSED
1. Applicable license amendments have been issued	NRR	01/25/94
2. Applicable exemptions have been granted	NA	NA
3. Applicable reliefs have been granted	NA	NA
4. Imposed Orders have been modified/rescinded	NA	NA
5. Confirmatory Action Letter conditions have been satisfied	PANEL	02/15/94
6. Significant enforcement issues have been resolved	PANEL	02/01/94
7. Allegations have been appropriately addressed	PANEL	02/01/94
8. 10 CFR 2.206 Petitions have been appropriately addressed	NRR	07/08/93
9. ASLB hearings completed	NA	NA
10. Licensee issuance of JCO related to Generic Letter 93-04, Rod Control System Failure and Withdrawal of Rod Control Cluster Assemblies	RIV/DRP	11/01/93

Reference Information

1. Auxiliary Feedwater testing Technical Specification Amendment 58 issued 01/25/94.
2. NA
3. NA
4. NA
5. This item includes licensee commitments in response to ORAT inspection (NRR letter of 01/27/94). The licensee provided a status of the CAL issues in a letter dated 01/29/94. Public meeting at the site on 02/14/94; 02/15/94 Panel meeting.



6. No outstanding enforcement issues affect restart. Discussed in Panel meeting 02/01/94.
7. No outstanding allegations affect restart. Discussed in Panel meeting 02/01/94.
8. Saporito Petition acknowledgement letter of 07/08/93
9. NA
10. JCO approved by plant managers 11/01/93.

C.6 COORDINATION WITH INTERESTED AGENCIES/PARTIES:

Coordination with other interested parties and agencies is important to ensure that concerns and requirements of these organizations are factored into the restart authorization.

ORGANIZATION	RESP ORG	DATE CLOSED
1. Federal Emergency Management Agency	RIV/NRR	02/03/94
2. Environmental Protection Agency	NA	NA
3. Department of Justice	PANEL	02/01/94
4. Department of Labor	PANEL	02/01/94
5. Appropriate State and Local Officials	RIV	02/14/94
6. Appropriate Public Interest Groups	RIV	02/14/94
7. Local News Media	RIV	02/14/94

Reference/Information

1. Completed per FEMA Region VI memo of 02/03/94.
2. NA
3. No DOJ restart restraints per L. Kokajko 02/01/94 (Reference: L. Kokajko memo to file dated 02/02/94).
4. No DOL restart restraints per L. Kokajko 02/01/94 (Reference: L. Kokajko memo to file dated 02/01/94).
5. Completed per 02/07/94 press release and issued meeting notice; public meeting 02/14/94.
6. Completed per 02/07/94 press release and issued meeting notice; public meeting 02/14/94.
7. Completed per 02/07/94 press release and issued meeting notice; public meeting 02/14/94.



D. PLANT SPECIFIC STARTUP ISSUES

The list of plant specific restart issues was developed from a review of the Diagnostic Evaluation Team Report, the Confirmatory Action Letter and supplements, the licensee's Operational Readiness Plan, routine and special NRC reports, the allegation process, and NRC staff actions assigned by the Executive Director for Operations following the Diagnostic Evaluation. NRC Inspection Report 50-498/499-9331 identified and assigned an Inspection Followup Item for each item related to issues which require resolution prior to the restart of either STP unit. This table will be updated periodically to reflect the status of inspection activities at STP.

The table following this page lists the plant-specific restart issues and their current status.

	RESTART ISSUE	RELATED ITEMS	DATE CLOSED
1	Turbine-driven Auxiliary Feedwater Pump Reliability and Testing Methodology	9331-07(9338-0) (9346-0) (9404-0), 08(9338-0) (9344-0) (9345-0) (9353-0), (9404-0), 09(9338-0) (9344-0) (9353-0) (9404-0), 10(9338-0) (9346-0), 43(9338-C), 50(9338-0), 71(9338-C) 9305-04(9338-C), 05(9338-0) (9406-C), 07(9338-C) Unit 1 LER 9307(9338-0) Unit 2 LER 9304(9338-0)	02/14/94 9338 9409
2	Station Problem Report Process, Threshold, Licensee's Review of Existing Reports for Issues Affecting Operability and Safe Plant Operation	9331-06(9338-0)(9354-C), 18(9344-0) (9345-0) (9354-0), 23(9354-0), 25(9406-C), 26(9354-0), 27(9354-0), 28(9344-0) (9354-C), 67(9354-C) 9235-02(9354-C) (9404-C) 9224-01(9354-C) (9404-C) 9321-01(9333-C) 9322-02(9333-C) 9308-02(9345-C), 04(9345-C)	02/01/94 9354
3	Service Request Backlog, Including Reduction Accomplished During the Current Outages and the Licensee's Review of Outstanding SRs for Issues Affecting Equipment Operability, Safe Plant Operation, and Operator Work-arounds	9331-02(9345-0) (9353-C), 03(9340-0), (9341-C) (9346-0) (9353-C), 07(9338-0) (9346-0), (9404-0), 08(9338-0) (9344-0) (9345-0) (9353-0), (9404-0), 09(9338-0) (9344-0) (9353-0) (9404-0), 29(9353-C), 31(9345-C), 37(9353-0), 38(9353-0), 39(9353-0), 47(9353-0), 49(9345-C) (9353-0), 62(9353-0), 79(9353-0) (9346- 0), 80(9353-C)	02/01/94 940E

RESTART ISSUE	RELATED ITEMS	DATE CLOSED
<p>4 The Postmaintenance Test Program, Including Corrective Actions in Response to Violations and Other Process Improvements and the Basis For the Licensee's Confidence That Equipment Removed From Service for Maintenance is Properly Restored to an Operable Status</p>	<p>9331-03(9340-0) (9341-C) (9346-0) (9353-C), 04(9337-0) (9346-0) (9353-0), 07(9338-0) (9346-0), (9404-0), 10(9338-0) (9346-0), 13(9339-0) (9344-0) (9346-0), 14(9339-C), 15(9346-0), 51, 63 (9346-C), 68(9339-C), 79(9353-0) (9346-0)            9226-03(9339-C) (9404-C)            9320-02(9339-C)            9305-01, 05, 07(9344-C)            Unit 1 LER 9204(9339-C), 9207(9339-C), 9214(9339-C), 9216(9339-C), 9305(9344-C)</p>	<p>02/01/94            9346            9354</p>
<p>5 The Outstanding Design Modifications, Temporary Modifications, and Other Engineering Backlog Items, Including the Licensee's Review of These For Issues Affecting Equipment Operability, Safe Plant Operation, and Operator Work-arounds</p>	<p>9331-02(9337-0) (9345-0) (9353-C), 04(9337-0) (9346-0), 08(9338-0) (9344-0) (9345-0) (9353-0), (9404-0), 12(9344-0), 16, 18(9344-0) (9345-0) (9354-0), 19(9344-0) (9345-C), 20(9404-C), 21(9404-C), 30(9345-0), 31(9345-C), 40(9345-C), 41(9345-0), 42(9345-0), 44(9404-C), 45(9404-C), 48(9345-C), 52(9338-0) (9345-C), 64(9345-C), 65(9340-0) (9341-C), 77(9345-C), 81(9345-C)            9208-01(9406-C)            9306-07(9353-0)            9315-01(9345-C)            Unit 1 LER 9220(9345-C), Unit 2 LER 9204(9345-C)</p>	<p>02/01/94            9355</p>

	RESTART ISSUE	RELATED ITEMS	DATE CLOSED
6	Adequacy of Operations Staffing	9331-01(9340-0) (9341-C), 03(9340-0) (9341-C) (9346-0) (9353-C), 24(9340-C), 56(9340-0) (9341-C), 57(9340-0) (9341-0) (9406-C), 59(9340-0) (9341-C), 60(9340-C), 65(9340-0) (9341-C), 66(9340-0) (9341-C), 73(9340-0) (9341-C) 9116-02(9340-0) (9341-0) (9406-C) 9304-03(9340-C), 04(9340-C) 9311-04(9340-C) 9322-01(9340-C) Unit 2 LERs 9305(9340-C), 9312(9340-C)	02/01/94 9341
7	Adequacy of Fire Brigade Leader Training and Qualifications	9331-04(9337-0) (9346-0), 33(9337-C), 75(9337-0) (9345-C)	02/01/94 9337
8	Adequacy of Fire Protection Computers and Software, the licensee's Success in Reducing the Number of Spurious Fire Protection System Alarms, and Other Fire Protection Hardware Problems	9331-02(9337-0) (9345-0) (9353-C), 04(9337-0) (9346-0), 17(9337-0) (9345-C), 22(9337-0) (9345-C), 58(9337-C), 75(9337-0) (9345-C) 9235-06(9337-0) 9309-01(9337-C)	02/01/94 9345

RESTART ISSUE		RELATED ITEMS	DATE CLOSED
9	Licensee Management's Effectiveness in Identifying, Pursuing, and Correcting Plant Problems	9331-04(9337-0)(9346-0), 05(9406-C), 06(9338-0)(9354-C), 17(9338-0) (9345-C), 18(9344-0) (9345-0) (9354-0), 22(9337-0) (9345-C), 23(9354-0), 25(9406-C), 32, 34, 35(9338-0) (9345-C), 37(9353-0), 46, 54(9406-C), 55(9343-0) (9406-C), 56(9340-0) (9341-C), 61(9406-C), 62(9353-0), 65(9340-0) (9341-C), 67(9354-C), 69, 70(9338-C), 72(9338-C), 73(9340-0) (9341-C), 80(9353-C), 82(9343-C) 9321-01, 9322-02 9224-01(9354-C) (9404-C) 9217-02(9406-C), 04 9303-01(9406-0) 9308-02(9345-C), 04(9345-C) Unit 1 LER 9204(9339-C)	02/01/94
10	NRC Review of the Effectiveness of the Licensee's SPEAKOUT Program	9331-78(9352-C)	02/01/94 9352
11	Standby Diesel Generator Reliability	9331-08(9338-0) (9344-0) (9345-0) (9353-0) (9404-0), 09(9338-0) (9344-0) (9353-0) (9404-0), 11(9344-C), 12(9344-0), 13(9344-0), 16, 19(9344-0) (9345-C), 28(9344-0) (9354-C) 9214-03(9344-C) 9221-03(9344-C) 9305-01(9344-C) 9315-03(9330-C) Unit 1 LER 9305(9344-C)	02/01/94 9344
12	Essential Chiller Reliability	9331-10(9338-0) (9346-0), 13(9344-0), 20(9404-C), 21(9404-C), 44(9404-C), 45(9404-C), 74(9404-C) 9224-03(9404-C)	02/01/94 9404

RESTART ISSUE		RELATED ITEMS	DATE CLOSED
13	Monitoring of the Licensee's System Certification Program	9331-35(9338-0) (9345-C), 53(9345-0)	02/01/94 9345
14	Adequacy of the Licensee's Resolution of the Reliability and Operability of the Feedwater Isolation Bypass Valves	9319-01 through 07(9335-C) 9324-01(9335-0) (9406-C) Unit 1 LER 9317(9335-C) Unit 1 LER 9320(9335-0) (9406-C) 9335-01(9406-C)	02/15/94 9406 9409
15	Tornado Damper Issues	9331-76(9342-C)	02/01/94 9342
16	Emergency Preparedness Accountability Issues	URI 498;499/9325-02(9347-C)	02/01/94 9347

Reference/Information

1. Resolved with exception of Mode 3 testing in IR 9338. Mode 3 testing completed IR 9409.
2. IR 9354 proposed closing this issue. ORAT found corrective action program to be weak, but improvements were in progress and program was adequate to support restart. Discussed in Panel meeting 02/01/94.
3. Progress noted in IR 9353. Followup in IR 9408. Discussed in Panel meeting 02/01/94.
4. Progress noted in IR 9339. Significant program improvement noted in IR 9346, but implementation weaknesses exist. Correction of weaknesses addressed in IR 5354. Discussed in Panel meeting 02/01/94.
5. Progress noted in IR 9345. Followup conducted in IR 9355. Discussed in Panel meeting 02/01/94.
6. Progress noted in IR 9340. Operator administrative workload reductions noted in IRs 9346 and 9353. Closed in IR 9341 dated 12/16/93. Discussed in Panel meeting 02/01/94.
7. Closed in IR 9337 dated 11/23/93. Discussed in Panel meeting 02/01/94.
8. Addressed in IR 9345. Discussed in Panel meeting 02/01/94.
9. Favorable observations with respect to fire protection issues in IR 9337. Favorable comments with respect to TDAFW issues in IR 9338. Favorable observations with respect to operator staffing issues in IRs 9339 and 9341. Favorable observations with respect to tornado damper issues in IR 9342. Good response to refueling machine problems noted in IR 9335. Good response to SR backlog noted in IR 9353. Favorable overall findings in IR 9343. Favorable findings with respect to PMT noted in IR 9346. Favorable observations with respect to standby diesel generators in IR 9344. Favorable observations in IR 9345. Addressed in IR 9355. Panel discussions on 01/27/94 and 02/01/94.

10. IR 9352 issued 01/21/94. Panel discussion on 02/01/94.
11. Addressed in IR 9344. Followup open items in IR 9355. Discussed in Panel meeting 02/01/94.
12. Addressed in IR 9404. Discussed in Panel meeting 02/01/94.
13. Favorable observations in IR 9336. Addressed in IR 9345. Discussed in Panel meeting 02/01/94.
14. Significant progress noted in IR 9335. Addressed in IR 9406. Mode 3 testing completed IR 9409.
15. Closed in IR 9342 dated 11/19/93. Discussed in Panel meeting 02/01/94.
16. Closed in IR 9347 dated 12/08/93. Discussed in Panel meeting 02/01/94.

E. RESTART INSPECTIONS

INSPECTION		RESP ORG	LEAD	SCHEDULE
1	TDAFW PUMPS	DRP	MAS	10/18/93 02/94
2	SPR PROCESS, THRESHOLD, REVIEW RESULTS	DRS	TOM +RI	10/12/93 12/13/93
3	SERVICE REQUEST BACKLOG STATUS AND REVIEW, EFFECT ON EQUIPMENT OPERABILITY, SAFE OPERATION, OPERATOR WORK-AROUNDS	DRP	MAS LDG MFR	11/29/93 12/06/93 01/24/94
4	POSTMAINTENANCE TEST PROGRAM	DRS	TOM RBV	10/25/93 11/29/93
5	ENGINEERING SACKLOGS	DRS	TFW	11/15/93
6	OPERATIONS STAFFING	DRS/DRP	JLP JIT	11/01/93 11/29/93
7	FIRE BRIGADE LEADER QUALIFICATIONS	DRS	GLC	10/18/93
8	FIRE PROTECTION COMPUTERS	DRS	GLC	10/18/93
9	MANAGEMENT EFFECTIVENESS IN IDENTIFYING, PURSUING, AND CORRECTING PLANT PROBLEMS	DRP/DRS/DRSS		EACH INSPECTION
10	SPEAKOUT REVIEW	DRS/HQ	DAP	11/29/93
11	EDG ISSUES	DRS/NRR	TFW	11/08/93 12/13/93 01/18/93
12	ESSENTIAL CHILLER ISSUES	DRP/NRR	MAS	01/03/94
13	SYSTEM CERTIFICATION	DRP/DRIL SRI/ORAT		12/93
14	FEEDWATER ISOLATION BYPASS VALVES	DRS	DAP	11/15/93 01/10/94
15	TORNADO DAMPERS	DRP/NRR	MAS	11/01/93
16	EP ACCOUNTABILITY	DRSS	BXM	11/18/93
17	LICENSEE'S READINESS ASSESSMENT	RIV/NRR	PANEL	12/93 - 01/94
18	ORAT	DRIL	JBJ	12/06/93 01/12/94