

Appendix A

NOTICE OF VIOLATION

Commonwealth Edison
Company

Docket No. 50-010
Docket No. 50-237
Docket No. 50-249

Based on the inspection conducted on September 5-8, 12-14, 20-22 and 26-28, 1978, it appears that certain of your activities were in noncompliance with NRC requirements, as noted below. The item is a deficiency.

Unit 3 Technical Specifications, Section 6.6.B.2, requires that the licensee report to the NRC within 30 days when reactor protection system instrument settings are found to less conservative than those established by Technical Specifications but which do not prevent fulfillment of the functional requirements of affected systems.

Contrary to the above, the licensee identified a nonconservative setting on Number 6 APRM Rod Block Trip Setpoint on June 6, 1978, and did not report it to the NRC until July 26, 1978. The licensee's corrective action to prevent recurrence has been implemented and reviewed and appears adequate; therefore, no further response is required.

7811300264