

CONTROL BLOCK: [] [] [] [] [] [] [] [] [] [] (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 P A S E S I 2 0 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 [] [] 5
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 20 26 LICENSE TYPE 30 37 CAT 39

CONT

0 1 REPORT SOURCE L 6 0 5 0 0 0 0 3 8 7 7 1 2 2 4 8 2 8 0 1 0 7 8 3 9
7 8 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During the Startup Testing Program, one main condenser Offgas Hydrogen Monitor
0 3 was declared inoperable, however, the required action statement was not met, in
0 4 that grab samples were not taken every 4 hours. This is reportable per T.S.
0 5 6.9.1.8.b. The redundant monitor did not indicate a hydrogen level in excess
0 6 of 40%, therefore no adverse consequences existed.

0 7
0 8

0 9 M C 11 A 12 X 13 Z Z Z Z Z Z 14 Z 15 Z 16
7 8 9 SYSTEM CODE 9 10 CAUSE CODE 11 12 CAUSE SUBCODE 13 14 COMPONENT CODE 15 16 COMP. SUBCODE 17 18 VALVE SUBCODE 19 20
17 LER/RO REPORT NUMBER 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32
EVENT YEAR 21 22 SEQUENTIAL REPORT NO. 23 24 OCCURRENCE CODE 25 26 REPORT TYPE 27 28 REVISION NO. 29 30
ACTION TAKEN 31 32 FUTURE ACTION 33 34 EFFECT ON PLANT 35 36 SHUTDOWN METHOD 37 38 HOURS 39 40 ATTACHMENT SUBMITTED 41 42 NPRD-4 FORM SUB. 43 44 PRIME COMP. SUPPLIER 45 46 COMPONENT MANUFACTURER 47 48
X 18 G 19 Z 20 Z 21 0 0 0 0 0 22 Y 23 N 24 Z 25 Z 9 9 9 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Positive communications between the Operations and Chemistry Groups was not made
1 1 when the action statement was entered. To prevent recurrence a temporary change
1 2 was made to the Incident Reporting Procedure to require Operation to initiate a
1 3 log and transmit it to chemistry to commence sampling. When Chemistry is
1 4 notified the action statement is cleared the log will be returned.

1 5 B 28 0 2 5 29 NA 30 A 31 Review of LCO log. 32
7 8 9 FACILITY STATUS 10 11 % POWER 12 13 OTHER STATUS 30 31 METHOD OF DISCOVERY 32 33 DISCOVERY DESCRIPTION 34 35

1 6 Z 33 Z 34 NA 35 NA 36
7 8 9 ACTIVITY CONTENT RELEASED OF RELEASE 10 11 AMOUNT OF ACTIVITY 35 36 LOCATION OF RELEASE 36 37

1 7 0 0 0 37 Z 38 NA 39
7 8 9 PERSONNEL EXPOSURES NUMBER 10 11 TYPE 12 13 DESCRIPTION 39 40

1 8 0 0 0 40 NA 41
7 8 9 PERSONNEL INJURIES NUMBER 10 11 DESCRIPTION 41 42

1 9 Z 42 NA 43
7 8 9 LOSS OF OR DAMAGE TO FACILITY TYPE 10 11 DESCRIPTION 43 44

2 0 N 44 NA 45
7 8 9 PUBLICITY ISSUED 10 11 DESCRIPTION 45 46

8301170488 830107
PDR ADOCK 05000387
S PDR

NAME OF PREPARER D. G. Mitchell

PHONE: 717-542-2181 Ext. 524

NRC USE ONLY

LICENSEE EVENT REPORT 82-067/017-0 ATTACHMENT

Upon the loss of one train of the Main Condenser Offgas Hydrogen Monitor, grab samples should have been initiated and continued every 4 hours. Failure to meet this action statement is reportable per T.S. 6.9.1.8.b. This determination was made during a review of the event on December 29, 1982. There were no adverse consequences because the redundant monitor and later grab sample showed a hydrogen concentrations within allowable limits.

The sampling was not initiated within the required time period because of poor communications between Operations and Chemistry personnel. Previous corrective actions to this recurring problem have included on Operating Instructions to require the Shift Supervisor to inform Chemistry personnel when to commence and discontinue Tech. Spec. related sampling. As an additional measure, the Incident Reporting Procedure has been temporarily changed to require Shift Supervision to initiate a Chemistry LCO log and transmit it to Chemistry. Chemistry will make entries for each required sample until such time when Shift Supervision verbally notifies Chemistry to stop sampling. Chemistry will present the completed form for Shift Supervision signature at which time it will be forwarded to the Sr. Compliance Engineer.

Operation and Chemistry are continuing to determine a more affective means of assuring Tech. Spec. action statement sampling is performed as required.

LER's of a similiar nature include:

82-038/03L-0

82-041/03L-0

82-042/01T-0