



CONNECTICUT YANKEE ATOMIC POWER COMPANY

HADDAM NECK PLANT

RR #1, BOX 127E, EAST HAMPTON, CONN. 06424

January 5, 1983

Mr. Ronald C. Haynes, Regional Administrator
Region 1, U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Reference: Facility Operating License No. DPR-61
Docket No. 50-213
Reportable Occurrence LER 83-001/1P

Dear Mr. Haynes:

In accordance with the requirements of I&E Bulletin 80-24 the following information concerning a containment recirculation fan cooler leak is hereby provided.

Water inventory checks by Operations personnel indicated an unknown source of water input to the reactor containment sump. An inspection within the reactor containment at 0650 hours identified a leaking tube in #4 reactor containment air recirculation fan cooler. The leak was isolated and the defective tube will be plugged.

A followup report will be submitted within 14 days.

Very truly yours,

Richard H. Graves
Station Superintendent

RHG/jhb

cc: Dir., Management Info. & Program Control, Washington, D. C. (2)
USNRC c/o Document Management Branch, Washington, D. C. (1)

8301170507 830105
PDR ADOCK 05000213
S PDR

IE29