

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 I L D R S 2 0 0 - 0 0 0 0 0 0 - 0 0 0 3 4 1 1 1 1 4 5

0 1 REPORT SOURCE L 0 5 0 0 0 2 3 7 1 2 0 7 8 2 1 2 2 2 8 2 9

0 2 During normal operation, the 2B CCSW pump was taken out of service without running
0 3 DOS 1500-6, Low Pressure Coolant Injection (LPCI) operability test. (Tech. Spec.
0 4 4.5.b.2) Safety significance was minimal since all ECCS systems were operable.
0 5 There was no effect on public health or safety. Previous occurrence of a missed
0 6 surveillance; R.O. 82-41, Docket 50-249.

0 7
0 8

0 9 SYSTEM CODE S B 11 CAUSE CODE A 12 CAUSE SUBCODE A 13 COMPONENT CODE Z Z Z Z Z Z 14 COMP. SUBCODE Z 15 VALVE SUBCODE Z 16

17 LER/RO REPORT NUMBER 8 2 21 EVENT YEAR 8 2 22 SEQUENTIAL REPORT NO. 0 5 1 24 OCCURRENCE CODE 0 3 28 REPORT TYPE L 30 REVISION NO. 0 32

1 0 Cause of the event was a failure to follow procedure. (Appendix X, Outage Report 1:
1 1 One CCSW pump inoperable). DOS 1500-6 was run and satisfactorily completed. Adher-
1 2 ence to procedure was reviewed with the personnel involved and will also be reviewed
1 3 in the six week operator training session. DOS 1500-6 will continue to be performed
1 4 monthly.

1 5 FACILITY STATUS E 28 % POWER 0 5 9 29 OTHER STATUS N/A 30 METHOD OF DISCOVERY A 31 DISCOVERY DESCRIPTION Operatic Review 32

1 6 ACTIVITY CONTENT Z 33 Z 34 N/A 35 AMOUNT OF ACTIVITY N/A 36 LOCATION OF RELEASE

1 7 PERSONNEL EXPOSURES 0 0 0 37 Z 38 N/A 39

1 8 PERSONNEL INJURIES 0 0 0 40 N/A 41

1 9 LOSS OF OR DAMAGE TO FACILITY Z 42 N/A 43

2 0 PUBLICITY ISSUED N 44 N/A 45

8301170516 821222
PDR ADOCK 05000237
S PDR

NAME OF PREPARER Lawrence Coyle

PHONE: 815-942-2920, X-526