

SAFEGUARDS INFORMATION

ORIGINAL RECORD COPY

MAR 11 1994

Docket Nos. 50-335, 50-389
License Nos. DPR-67, NPF-16

Florida Power and Light Company
ATTN: Mr. J. H. Goldberg
President - Nuclear
P. O. Box 14000
Juno Beach, FL 33408-0420

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NOS. 50-335/94-02 AND 50-389/94-02

This refers to the inspection conducted by A. Tillman of this office on February 7 - 11, 1994. The inspection included a review of activities authorized for your St. Lucie facility. At the conclusion of the inspection, the findings were discussed with those members of your staff identified in the enclosed report.

The enclosed Inspection Report identifies activities that violated NRC requirements that will not be subject to enforcement action because the licensee's efforts in identifying and/or correcting the violation meet the criteria specified in Section VII.B. of the Enforcement Policy.

Within the scope of the inspection, violations or deviations were not identified.

The material enclosed herewith contains Safeguards Information as defined by 10 CFR Part 73.21 and its disclosure to unauthorized individuals is prohibited by Section 147 of the Atomic Energy Act of 1954, as amended. Therefore, the material will not be placed in the Public Document Room.

Should you have any questions concerning this letter, please contact us.

Sincerely,

Disposal signed by
E. McAlpine
DM Douglas M. Collins, Chief
Nuclear Materials Safety and
Safeguards Branch
Division of Radiation Safety
and Safeguards

Enclosure: (See page 2)

9403220074 940311
PDR ADDCK 05000335
G PDR

SAFEGUARDS INFORMATION

JECH

SAFEGUARDS INFORMATION

Florida Power and Light Company

3

MAR 11 1994

(cc w/Inspection Summary cont'd)
Joe Myers, Director
Division of Emergency Preparedness
Department of Community Affairs
2740 Centerview Drive
Tallahassee, FL 32399-2100

Thomas R. L. Kindred
County Administrator
St. Lucie County
2300 Virginia Avenue
Ft. Pierce, FL 34982

Charles B. Brinkman
Washington Nuclear Operations
ABB Combustion Engineering, Inc.
12300 Twinbrook Parkway, Suite 3300
Rockville, MD 20852

bcc w/encl:
NRR/DRSS/PSGB

bcc w/Inspection Summary:
K. Landis, RII
J. Norris, NRR
Document Control Desk (RIDS IE04), 016

NRC Resident Inspector
U.S. Nuclear Regulatory Comm.
7585 South Highway A1A
Jensen Beach, FL 34957-2010

RII:DRSS
[Signature]
TILLYMAN
03/10/94

RII:DRSS
[Signature]
MCGUIRE
03/11/94

RII:DRP
[Signature]
LANDIS
03/11/94

SAFEGUARDS INFORMATION

SAFEGUARDS INFORMATION

Florida Power and Light Company 2

MAR 11 1994

Enclosure:
NRC Inspection Report
(Safeguards Information)

cc w/encl:
D. A. Sager
Vice President
St. Lucie Nuclear Plant
P. O. Box 128
Ft. Pierce, FL 34954-0128

H. N. Paduano, Manager
Licensing and Special Projects
Florida Power and Light Company
P. O. Box 14000
Juno Beach, FL 33408-0420

C. L. Burton
Plant General Manager
St. Lucie Nuclear Plant
P. O. Box 128
Ft. Pierce, FL 34954-0128

cc w/Inspection Summary:
Harold F. Reis, Esq.
Newman & Holtzinger
1615 L Street, NW
Washington, D. C. 20036

John T. Butler, Esq.
Steel, Hector and Davis
400 Southeast Financial Center
Miami, FL 33131-2398

Bill Passeti
Office of Radiation Control
Department of Health and
Rehabilitative Services
1317 Winewood Boulevard
Tallahassee, FL 32399-0700

Jack Shreve
Public Counsel
Office of the Public Counsel
c/o The Florida Legislature
111 West Madison Avenue, Room 812
Tallahassee, FL 32399-1400

(cc w/Inspection Summary cont'd - See page 3)

SAFEGUARDS INFORMATION



SAFEGUARDS INFORMATION

UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION II
101 MARIETTA STREET, N.W., SUITE 2900
ATLANTA, GEORGIA 30323-0199

Report Nos. 50-335/94-02 and 50-389/94-02

Licensee: Florida Power and Light Company
9250 West Flagler Street
Miami, FL 33102

Docket Nos. 50-335 and 50-389

License Nos. DPR-67 and NPF-16

Facility Name: St. Lucie 1 and 2

Inspection Conducted: February 7 - 11, 1994

Inspector: *Stephen M. Masny* 3-11-94
A. Tillman, Safeguards Inspector Date Signed

Approved by: *D. McGuire* 3/18/94
D. McGuire, Chief Date Signed
Safeguards Section
Nuclear Materials Safety and Safeguards Branch
Division of Radiation Safety and Safeguards

SUMMARY

Scope:

This routine, announced inspection was conducted in the areas of the Physical Security Program for Power Reactors, specifically: Management Support, Security Program Plans and Audits; Physical Barriers - Protected and Vital Areas; Access Control - Personnel, Packages and Vehicles; Assessment; Compensatory Measures; and Alarm Stations and Communications.

Results:

In the areas inspected, a non-cited violation was identified. Inspection results confirmed that the security force continues to perform at an acceptable level and is capable of providing adequate protection for vital resources and safety related equipment. Security force management and personnel performance were notable.

A licensee identified and reported Safeguards Event, LER 93-S02, relating to a failure to provide required compensatory measures in response to a security computer system failure was confirmed. Review and discussion with security management personnel verified that the licensee had implemented adequate corrective action. The violation will not be subject to enforcement action because the licensee's efforts in identifying and correcting the violation meet the criteria specified in Section VII.B. of the Enforcement Policy.

9403220078 940311
PDR ADDCK 05000335
G PDR

Document transmitted herewith
contains sensitive unclassified
information. When separated from
enclosures, this document is decontrolled

SAFEGUARDS INFORMATION

2

Further review revealed that the licensee was continuing to experience failures in the security computer system, or components of the system, the cause of which had not been identified. Five system failures had occurred since January 1, 1994. Review confirmed that appropriate compensatory measures had been implemented in each instance of these system failure. Efforts were ongoing by the licensee to resolve the problem.

SAFEGUARDS INFORMATION

Document transmitted herewith
contains sensitive unclassified
information. When separated from
enclosures, this document is decontrolled