



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401-1927
Telephone (612) 330-5500

March 16, 1994

U S Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

PRAIRIE ISLAND NUCLEAR GENERATING PLANT
Docket No. 50-306 License No. DPR-60

Unit 2 Inservice Inspection Summary Report
Refueling Outage No. 16

During the 1993 Prairie Island Unit 2 refueling outage (Refueling Outage No. 16), the inservice inspection (ISI) examination for period three of the second 10 year interval was conducted. Attached for your information are four copies of the ISI examination Summary Report for this period.

The report identifies components examined, the examination methods used, the examination number, and summarizes the results. All anomalies were either corrected or an engineering evaluation was performed to accept "as is" conditions. A description of the corrective work and the corresponding work request numbers are provided in the ASME Section XI Repair/Replacement portion of the report.

This Summary Report is being submitted in accordance with the Prairie Island ASME Code Section XI Inservice Inspection and Testing Program and is intended to satisfy the inspection reporting requirements contained in IWA-6220 of the ASME Boiler and Pressure Vessel Code.

Sincerely,

Roger O Anderson
Director
Licensing and Management Issues

- c: Regional Administrator III, NRC (2 copies of attachment)
- NRR Project Manager, NRC (1 copy of attachment)
- Senior Resident Inspector, NRC (w/o attachment)
- J E Silberg (w/o attachment)
- Chief Boiler Inspector, State of MN (1 copy of attachment)
- Paul Fisher, Hartford Ins. (1 copy of attachment)

Attachment

File: PI2_ISR.RPT

9403220093 940316
PDR ADDCK 05000306
Q PDR

ACAY
1/1