

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 I L D R S 2 0 0 0 - 0 0 0 0 0 0 - 0 0 0 3 4 1 1 1 1 4 5

01 L 0 0 5 0 0 0 2 3 7 1 2 1 5 8 2 0 1 0 3 8 2 9

02 During normal operation, while performing LPCI Valve Operability Surveillance (DOS 1500-1) the 2A LPCI Heat Exchanger Bypass Valve (1501-11A) position indication was lost. Safety significance was minimal since LPCI was operable. Similar occurrences as referenced per DVR #12-3-80-6, 12-2-82-37.

09 S F E A C K T B K R B Z

17 8 2 0 5 3 0 3 L 0 Z 18 X 19 20 21 0 0 0 0 N 23 Y 24 N 25 G 0 8 0 26

10 Exact cause of the event could not be determined because after breaker was reset, 11 the valve was successfully operated three times from control room. Breaker setting 12 will be checked during refuel outage and DOS 1500-1 will continue to be performed 13 monthly.

15 E 0 5 5 N/A B Surveillance Testing

16 Z 2 N/A

17 0 0 0 2 N/A

18 0 0 0 N/A

19 2 N/A

20 N B301180347 830103 PDR ADOCK 05000237 PDR