

P.O. BOX 770 HARVFORD, CONNECTION 05101 (200) 886-5211

November 6. 1980

MP-1-1652) NOV 10 PH 5 01

Mr. Boyce H. Grier
Director, Region I
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia. PA 19405

Reference:

Provisional License DPR-21

Docket Number 50-245

Reportable Occurrence RO-80-19/1P

Dear Mr. Grier:

This Tetter is forwarded to provide prompt notification of Reportable Occurrence RO-80-19/IP as required by the Hillstone Unit I Technical Specifications.

On November 6, 1980 at 0925 hours during performance of Class II Inservice Inspection of the Isolation Condenser System, liquid penetrant examination of the inside diameter of the steam supply piping nozzle-to-isolation condenser vessel weld revealed circumferential cracking on both sides of the weld in the heat affected zone. The cause of weld cracking is not known at the present time; an investigation is in progress.

The plant is shut down for a planned refueling outage and the Isolation Condenser System is out of service. It will remain out of service pending investigation of the incident and completion of repair activities.

Additional information including results of the investigation and corrective action will be included in a 14 day follow-up report.

Yours truly,

MORTHEAST NUCLEAR ENERGY COMPANY

THIS DOCUMENT CONTAINS
POOR QUALITY PAGES

SJ. Mroczka

S:atfom Superintendent

Millstone Muclear Power Station

EJM/MJB: kaf

cc: Director, Office of Management Information and Program Control, Washington, D.C. (2)

U.S. Muclear Regulatory Commission, c/o Document Management

Branch, Washington, D.C. 20555

8011120 537

MOO"