



January 11, 1983  
L-83-14

JAN 14 1983  
REG. DIVISION

Mr. James P. O'Reilly  
Regional Administrator, Region II  
U. S. Nuclear Regulatory Commission  
101 Marietta Street, Suite 300  
Atlanta, Georgia 30303

Re: St. Lucie Unit 2  
Docket No. 50-389, 10 CFR 50.55(e), 82-002  
Fan Belt Problems During Initial Start-Up of Diesel Generator

Dear Mr. O'Reilly:

On February 10, 1982, Florida Power and Light Company (FPL) notified the Region II Office of Inspection and Enforcement, in accordance with the requirements of 10 CFR 50.55(e), of a potential deficiency regarding the fan belts on diesel generators 2A and 2B. An interim report submitted to you on November 24, 1982 (L-82-517) stated that a final report would be submitted by January 20, 1983. We are still working on this problem and expect to submit a final report by February 8, 1983.

Very truly yours,

Robert E. Uhrig  
Vice President  
Advanced Systems & Technology

REU/JC/cab

cc: Director of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

OFFICE COPY  
IE 27

8301180396 830111  
PDR ADDCK 05000389  
S PDR