

MISSISSIPPI POWER & LIGHT COMPANY Helping Build Mississippi

P. O. BOX 1640, JACKSON, MISSISSIPPI 39205

February 7, 1983

JAMES P. McGAUGHY, JR. ASSISTANT VICE PRESIDENT

Office of Inspection & Enforcement U. S. Nuclear Regulatory Commission Region II 101 Marietta St., N.W., Suite 3100 Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Regional Administrator

Dear Mr. O'Reilly:

SUBJECT: Grand Gulf Nuclear Station

Unit 1 Docket No. 50-416 License No. NPF-13 File 0260/L-835.0

Redundant Division Raceway

Fire Protection

Deficiencies Discovered

000

Cus

LER 83-010/99 X-0

AECM-83/86

On January 5, 1983, during an inspection of completed work which corrected fire protection deficiencies on redundant raceways/cables, Maintenance Field Engineering noted similar deficiencies in the Auxiliary Building, Turbine Building, and Control Building. Fire watches were established in accordance with Technical Specification 3.7.7.a. Attached LER 83-010/99 X-0 is submitted as a Special Report pursuant to Technical Specification 3.7.7.a.

for J. P. M'Garghy

JPM: sap Attachment

cc: Mr. N. L. Stampley (w/a)

Mr. R. B. McGehee (w/o)

Mr. T. B. Conner (w/o)

Mr. G. B. Taylor (w/o)

Mr. Richard C. DeYoung, Director (w/a) Office of Inspection & Enforcement U. S. Nuclear Regulatory Commission Washington, D. C. 20555

Document Control Desk (w/a) U. S. Nuclear Regulatory Commission Washington, D. C. 20555

TE 12