



February 4, 1983

Kewaunee Nuclear Power Plant

ATTACHMENT TO LER 83-001

Cause Description & Corrective Actions (27)

An Electrician was repairing a light socket in RR175 and pulled the fuse to deenergize it, this in turn deenergized SV33379. Immediate actions were taken to proceed to a hot shutdown utilizing normal operating procedures. Chemistry refilled the tank to its required TS level and the Plant was returned to 100% power. A design change is nearly complete which will prevent this from happening again.