


550 West 17th South P O Box 687 Salt Lake City, Utah 84110

801 973 2500

January 26, 1983

U.S. Nuclear Regulatory Commission Region IV 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76012



Re: Docket No. 99900784/82-1

Gentlemen:

In regards to your letter written to us on January 4, 1983 we have responsed to the additional information that you have requested.

Our response is as follows:

- 1. All of the items are documented in the individual's Training/ Indoctrination Records.
- 2. The Nuclear QA Co-ordinator has been instructed to review the Non-conformance Control List and the Control List for the Shop Checklists to make sure there are no nonconformances or outstanding items remaining prior to release of material for shipment.
- 3. Guidelines have been established for controlling repairs. The use of the Group Repair Entry (formerly referred to as General Repair Entry) has been limited to minor surface and edge defects. All other repairs are reviewed by the Nuclear QA Co-ordinator, and are controlled by and documented on a repair checklist or a separate line entry on an existing checklist. The Shop checklists and OA Handbook which contain the procedures are now located in each welding department area where work of this nature is being performed.

Very truly yours CHICAGO BRIDGE & IRON CO.

Ronald A. Bonina

Quality Assurance Superintendent.

Hourse)

RAB/fd