APPENDIX A

NOTICE OF VIOLATION

Carolina Power & Light Company Brunswick 1 and 2

Docket Nos. 50-325 and 50-324 License Nos. DPR-71 and DPR-62

As a result of the inspection conducted on October 15 - November 15, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified.

Technical Specification 3.7.8 requires all fire barrier penetrations, including cable penetration barriers, fire doors and fire dampers, in fire boundaries protecting safety-related areas, shall be functional.

Contrary to the above, on October 26, cable penetration barriers in each unit's cable spreading room were not functional, in that the fire stop seals of these penetrations had been removed for plant modification work and not replaced. The integrity of the penetrations was last verified by the licensee on September 3, 1982.

This is a Severity Level V Violation (Supplement I.).

Pursuant to the provisions of 10 CFR 2.201, you are hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

	BEC	0	6	1982
Date:				