

# SAFETY INSPECTION

1. LICENSEE Roof Inspection Services of Virginia, Inc. 2005 Greenbrier Road Chesapeake, Virginia 23320		2. REGIONAL OFFICE REGION II U S NUCLEAR REGULATORY COMMISSION 101 MARIETTA STREET NW SUITE 2900 ATLANTA GA 30323	
3. DOCKET NUMBER(S) 030-17196	4. LICENSE NUMBER(S) 45-19238-01	5. DATE OF INSPECTION 2/16/94	

**LICENSEE:**

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The findings as a result of this inspection are as follows:

- 1. Within the scope of this inspection, no violations were observed. *See Item # 4.*
- 2. The inspector also verified the steps you have taken to correct the violations identified during the last inspection. We have no further questions on those actions at this time.
- 3. During this inspection certain of your activities, as described below or attached, were in violation of NRC requirements. This form is a **NOTICE OF VIOLATION**, which is required to be posted in accordance with 10 CFR 19.1.
  - A. \_\_\_\_\_ was not properly posted to indicate the presence of a \_\_\_\_\_ 10 CFR 20.203(b),(c),(d),(e) or 34.42.
  - B. \_\_\_\_\_ of sealed sources were not performed at the proper frequencies. 10 CFR \_\_\_\_\_ or License Condition Number \_\_\_\_\_.
  - C. Records of \_\_\_\_\_ were not properly maintained. 10 CFR \_\_\_\_\_ or License Condition Number \_\_\_\_\_.
  - D. Documents were not properly posted or otherwise made available. 10 CFR 19.11.
  - E. Reports or notification of \_\_\_\_\_ were not made in accordance with 10 CFR \_\_\_\_\_ or License Condition Number \_\_\_\_\_.
  - F. \_\_\_\_\_

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified in the items checked above. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201. No further response will be submitted unless required by the NRC.

SIGNATURE - LICENSEE 9403250158 PDR ADDOCK C	DATE 940216 03017196 PDR	SIGNATURE - NRC INSPECTOR <i>[Signature]</i>	DATE 2/16/94
---	-----------------------------------	---	-----------------

011 FEO7

# SAFETY INSPECTION

1. LICENSEE Roof Inspection Service of Virginia 2005 Greenbrier Road, Suite 204 Chesapeake, Virginia 23320		2. REGIONAL OFFICE REGION II U.S. NUCLEAR REGULATORY COMMISSION 101 MARIETTA STREET NW SUITE 2900 ATLANTA GA 30323	
3. DOCKET NUMBER(S)  030-17196	4. LICENSE NUMBER(S)  45-19238-01	5. DATE OF INSPECTION  2/16/94	

3. (Continued)

G. \_\_\_\_\_

\_\_\_\_\_

H. \_\_\_\_\_

\_\_\_\_\_

I. \_\_\_\_\_

\_\_\_\_\_

4. The violations listed below are not being cited because they were self-identified, and corrective action was or is being taken, and the remaining criteria in 10 CFR 2, App. C, to exercise discretion were satisfied.

A. Shipping papers do not contain the hazard class or RQ (49 CFR 172.200-604)

\_\_\_\_\_

B. Shipping container was not marked with RQ (49 CFR 172.300)

\_\_\_\_\_

C. Parts 19, 20, 21, the License or Application, or a statement indicating where these documents could be removed was not posted.

\_\_\_\_\_

EE07