

APPENDIX A

NOTICE OF VIOLATION

Florida Power and Light
St. Lucie 2

Docket Nos. 50-389
License No. CFPB-144

As a result of the inspection conducted on November 16-19, 1982, and in accordance with the NRC Enforcement Policy, 47 FR 9987 (March 9, 1982), the following violation was identified.

10 CFR 50, Appendix B, Criterion IX as implemented by FPL Topical Report (FP&L TQARI-76A) Section 9 requires measures be established to assure special processes including nondestructive testing are controlled. Licensee procedure QI-9.1 establishes visual inspection requirements.

Contrary to the above, measures were inadequate to control nondestructive testing in that between May 11-14, 1982, two examples of undersize safety related socket weld joints, which had been visually inspected and accepted were noted. In addition, one example of a safety related pipe weld which had been visually inspected and did not meet the 3 to 1 taper transition requirements were noted.

This is a Severity Level IV Violation (Supplement II).

Date: JAN 13 1983