

DUKE POWER COMPANY

P.O. BOX 33189
CHARLOTTE, N.C. 28242

HAL B. TUCKER
VICE PRESIDENT
NUCLEAR PRODUCTION

TELEPHONE
(704) 373-4531

03 FEB 10 10 56
February 1, 1983

Mr. James P. O'Reilly, Regional Administrator
U. S. Nuclear Regulatory Commission
Region II
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303


Re: RII:RCD
McGuire Nuclear Station
Docket Nos. 50-369 and 50-370
IE Bulletin 82-04

Dear Mr. O'Reilly:

This letter is in response to IE Bulletin 82-04 which concerned deficiencies in primary containment electrical penetration assemblies. McGuire Nuclear Station Units 1 and 2 have no Bunker Ramo electrical penetrations using the hard epoxy module design installed, nor are any planned to be installed in any safety related system.

I declare under penalty of perjury that the statements set forth herein are true and correct to the best of my knowledge.

Very truly yours,



Hal B. Tucker

WHM/php

cc: Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Senior Resident Inspector
McGuire Nuclear Station

8302150526 830201
PDR ADOCK 05000369
Q PDR

IE11