LICENSELEVANIA
CONTROL BLOCK [] [] [] [PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION]
O 1 3 C A R S S 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 5 CAT 58
CON'T REPORT 6 0 5 0 0 0 0 3 1 2 7 0 5 0 5 8 2 3 0 8 1 1 8 2 9 SOURCE SOURCE SO SOURCE SOURCE SO SOURCE
On May 5, 1982, while the unit was in cold shutdown, the "A" Decay
Heat pump inboard bearing was found to be leaking oil. Since the
unit was in cold shutdown, the only consequence was the changing over
to the "B" Decay Heat pump. There were no effects on plant or
ole public safety.
07
7 8 9 SYSTEM CAUSE CAUSE COMP. VALVE
CODE SUBCODE S
17 REPORT NUMBER
ACTION FUTURE SPECT SHUTDOWN HOURS 22 ATTACHMENT SUBMITTED FORM SUB. SUPPLIER MANUFACTURER MANUFACTURER SUPPLIER SUPPLIE
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) The cause cannot be clearly determined. The pump inboard bearing cover
was removed, hydro tested and air tested, with no indication of leakage. The
mechanical seals were inspected and found to be satisfactory. The pump was
1 3 Tourid to be strightery out of dirighments, so it has to
pump has been in service for several days and has shown no oil leakage.
STATUS STATUS OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 N/A ODSERVATION BY OPERATION 32 N/A 31 Observation by Operations Staff
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) N/A LOCATION OF RELEASE (36) N/A
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)
1 7 0 0 0 37 Z 38 N/A
N/A
LOSS OF OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION N/A
PUBLICITY SSUED DESCRIPTION 45
2 0 Y 44 Local newspapers and wire services.
NAME OF PREPARER R. W. Colombo PHONE: (916) 452-3211